

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number
 EPA ID Number

Database(s)

LA CO SHERIFF ALTADENA STA (Continued)

U003775909

Piping Construction (Aboveground) :		
Single Wall :		Not reported
Double Wall :		Not reported
Unknown :		Not reported
Other :		Not reported
Piping Manufacturer (Aboveground) :		Not reported
Piping Mat. And Corrosion Protection (Underground) :		
Bare Steel :		Not reported
Stainless Steel :		Not reported
Plastic Compatible With Contents :		Not reported
Fiberglass :		Not reported
Steel W/coating :		Not reported
FRP Compatible W/100% Methanol :		Not reported
Galvanized Steel :		Not reported
Flexible (HDPE - High Density Polyethylene) :		Not reported
Cathodic Protection :		Not reported
Unknown :		Not reported
Other :		Not reported
Piping Mat. & Corrosion Protec (Aboveground) :		
Bare Steel :		Not reported
Stainless Steel :		Not reported
Plastic Compatible With Contents :		Not reported
Fiberglass :		Not reported
Steel W/coating :		Not reported
Frp Compatible W/100% Methanol :		Not reported
Galvanized Steel :		Not reported
Flexible (HDPE - High Density Polyethylene) :		Not reported
Cathodic Protec :		Not reported
Unknown :		Not reported
Other :		Not reported
Piping Leak Detection (Underground - Single Wall) :		
Electronic Line Leak Detector/ Auto Shutoff/ Alarms :		Not reported
Monthly 0.2 Gph Test :		Not reported
Annual Integrity Test :		Not reported
Daily Visual Monitrng , Trienn Integrity Test :		Not reported
Self Monitoring :		Not reported
Biennial Integrity Test :		Not reported
Piping Leak Detection (Secondarily Contained) :		
Sump Sensor, Alarms ,Auto Shutoff For Leaks :		Not reported
Sump Snsr, Alrm ,Auto Shutoff For Leaks, Failure, & Disconnect :		Not reported
Sump Sensor ,Alarms ,No Auto Shutoff :		Not reported
Pressure, Auto Leak Detctr ,Flow Shutoff Or Restrictn		Not reported
Annual Integrity Test :		Not reported
Suction,Gravity , Sump Sensor,Alarms :		Not reported
Piping Leak Detection (Emergency Generators) :		
Sump Sensor W/O Auto Shutoff /Alarms :		Not reported
Auto Leak Detector W/O Flow Shutoff Or Restrictn :		Not reported
Annual Integrity Test :		Not reported
Piping Leak Detecn Abvegrnd - Emrgncy Gen - Daily Visual Chk :		Not reported
Pipe Integrity Test, Underground :		Not reported
Piping Leak Detection (Aboveground - Single Wall) :		
Electronic Line Leak Detector /Auto Shutoff /Alarms :		Not reported
Monthly 0.2 Gph Test :		Not reported
Annual Integrity Test :		Not reported
Single Wall, Pressure Daily Visual Check :		Not reported
Single Wall, Suction - Daily Visual Monitoring :		Not reported
Triennial Integrity Test :		Not reported

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number
 EPA ID Number

Database(s)

LA CO SHERIFF ALTADENA STA (Continued)

U003775909

Self Monitoring :	Not reported
Single Wall, Gravity - Daily Visual Monitoring :	Not reported
Biennial Integrity Test :	Not reported
Piping Leak Detection (Aboveground - Secondary Contained)	
Sump Sensor, Alarms, Auto Shutoff For Leaks :	Not reported
Piping Leak Detection (Underground - Secondary Contained)	
Sump Snsr, Alrm , Auto Shutoff For Leaks, Failre & Disconct :	Not reported
Sump Sensor, Alarms, No Auto Shutoff :	Not reported
Pressure - Auto Leak Detctr, Flow Shutoff /Restrctrn :	Not reported
Annual Integrity Test :	Not reported
Suction/gravity - Sump Sensor , Alarms :	Not reported
Piping Leak Detection Underground (Emergency Generators)	
Sump Sensor Without Auto Shutoff , Alarms :	Not reported
Auto Leak Detector W/o Flow Shutoff Or Restrctrn :	Not reported
Annual Integrity Test :	Not reported
Daily Visual Check :	Not reported
Pipe Integrity Test, Aboveground :	Not reported
Date Dispenser Containment Installed :	Not reported
Dispenser Containment Type :	Not reported
Date Certified (Tank Unit) :	Not reported
Owner/ Operator Name (Tank Unit) :	Not reported
Owner/ Operator Title (Tank Unit) :	Not reported
Permit Number :	Not reported
Permit Approved By :	Not reported
Permit Expiration Date :	Not reported
Last Annual Monitoring Cert:	Not reported
Secondary Containment Test :	Not reported
Spill Containment Present :	Not reported
Drop Tube Present :	Not reported
Striker Plate Present :	Not reported
Alarm Present :	Not reported
Ball Float Present :	Not reported
Fill Tube Present :	Not reported
Other Tank Leak Detection Present :	Not reported

27

THREE CORNERS RESTAURANT
2555 N LAKE AVE
UNINCORPORATED, CA

LOS ANGELES CO. HMS **S102058861**
N/A

HMS:

Facility Id:	016832-022492		
Facility Type:	Not reported		
Permit Number:	Not reported	Permit Status:	Not reported
Facility Status:	OPEN	Area:	3
Region:	Los Angeles County:		

27

ARCO PRODUCTS CO
2571 N LAKE AVE
UNINCORPORATED, CA

LOS ANGELES CO. HMS **U003060462**
N/A

HMS:

Facility Id:	004258-104411		
Facility Type:	100		
Permit Number:	000001976	Permit Status:	Closed
Facility Status:	Closed	Area:	3
Region:	Los Angeles County:		

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)Site		Database(s)	EPA ID Number

28	CLIFFORD BEYERS 636 ROYCE ST ALTADENA, CA 91001	HAZNET	S103667737 N/A
-----------	--	---------------	---------------------------------

HAZNET:

Gepaid:	CLU970018351
Tepaid:	AZD049318009
Gen County:	Los Angeles
Tsd County:	99
Tons:	.2709
Category:	Laboratory waste chemicals
Disposal Method:	Transfer Station
Contact:	Not reported
Telephone:	(000) 000-0000
Mailing Address:	PO BOX 806
	SACRAMENTO, CA 95812 - 0806
County	Los Angeles

29	CAL PACIFIC SALVAGE INC. 796 FONTANET WY ALTADENA, CA 91001	LUST Cortese	S100227947 N/A
-----------	--	-------------------------------	---------------------------------

State LUST:

Cross Street:	EL MOLINO	
Qty Leaked:	Not reported	
Case Number	042889-02	
Reg Board:	Los Angeles Region	
Chemical:	Gasoline	
Lead Agency:	Local Agency	
Local Agency :	19000	
Case Type:	Soil only	
Status:	Pollution Characterization	
County:	Los Angeles	
Review Date:	Not reported	Confirm Leak: Not reported
Workplan:	Not reported	Prelim Assess: Not reported
Pollution Char:	Not reported	Remed Plan: Not reported
Remed Action:	Not reported	Monitoring: Not reported
Close Date:	Not reported	
Release Date:	3/22/1989	
Cleanup Fund Id :	Not reported	
Discover Date :	1/1/1965	
Enforcement Dt :	Not reported	
Enf Type:	Not reported	
Enter Date :	Not reported	
Funding:	Not reported	
Staff Initials:	Not reported	
How Discovered:	Tank Closure	
How Stopped:	Not reported	
Interim :	Not reported	
Leak Cause:	UNK	
Leak Source:	Tank	
MTBE Date :	Not reported	
Max MTBE GW :	Not reported	
MTBE Tested:	Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.	
Priority:	Not reported	
Local Case # :	Not reported	
Beneficial:	Not reported	
Staff :	JLC	
GW Qualifier :	Not reported	
Max MTBE Soil :	Not reported	
Soil Qualifier :	Not reported	

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number
 Database(s) EPA ID Number

CAL PACIFIC SALVAGE INC. (Continued)

S100227947

Hydr Basin #: Not reported
 Operator : Not reported
 Oversight Prgm: Local Implementing Agency UST (includes non-LOP cases within LOP jurisdiction)
 Oversight Prgm : LIA
 Review Date : 4/28/1989
 Stop Date : Not reported
 Work Suspended :Not reported
 Responsible Party:CAL PACIFIC SALVAGE INC.
 RP Address: 7930 MARBRISA ST, HUNTINGTON PARK, CA 90255
 Global Id: T0603700076
 Org Name: Not reported
 Contact Person: Not reported
 MTBE Conc: 0
 Mtbe Fuel: 1
 Water System Name: Not reported
 Well Name: Not reported
 Distance To Lust: 0
 Waste Discharge Global ID: Not reported
 Waste Disch Assigned Name: Not reported

LUST Region 4:
 Report Date: 3/22/1989
 Lead Agency: Local Agency
 Local Agency: 19000
 Case Number: 042889-02
 Substance: Gasoline
 Case Type: Soil
 Status: Pollution Characterization
 Region: 4
 Staff: Not reported

CORTESE:
 Reg Id: 042889-02
 Region: CORTESE
 Reg By: Leaking Underground Storage Tanks

29

**TOMS AUTO SERVICE
 796 E FONTANET WAY
 UNINCORPORATED, CA**

**LOS ANGELES CO. HMS U003059731
 N/A**

HMS:
 Facility Id: 003453-103572
 Facility Type: I01
 Permit Number: 000010701
 Facility Status: Closed
 Region: Los Angeles County:
 Permit Status: Closed
 Area: 3

30

**1X L A COUNTY SHERRIFS DEPT
 780 ALTADENA DRIVE
 ALTADENA, CA 00000**

**HAZNET S102798793
 N/A**

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

1X L A COUNTY SHERRIFS DEPT (Continued)

S102798793

HAZNET:

Gepaid: CAC000938888
 Tepaid: CAL000027741
 Gen County: Los Angeles
 Tsd County: 5
 Tons: .8428
 Category: Asbestos-containing waste
 Disposal Method: Disposal, Land Fill
 Contact: THE COUNTY OF LOS ANGELES
 Telephone: (000) 000-0000
 Mailing Address: STARS ATTN: G BROWM
 WHITTIER, CA 90605
 County: Los Angeles

30 LA CO SHERIFF STATION LOS ANGELES CO. HMS U003058377
 780 E ALTADENA DR N/A
 UNINCORPORATED, CA

HMS:

Facility Id: 002001-I02078
 Facility Type: I01
 Permit Number: 00004321C Permit Status: Permit
 Facility Status: Permit Area: 3
 Region: Los Angeles County:

30 LA CO SHERIFF ALTADENA STA LOS ANGELES CO. HMS S102056879
 780 E ALTADENA DR N/A
 UNINCORPORATED, CA

HMS:

Facility Id: 002001-002078
 Facility Type: T0
 Permit Number: 00004670T Permit Status: Permit
 Facility Status: Permit Area: 3
 Region: Los Angeles County:

31 FAIR OAKS BURGER LOS ANGELES CO. HMS U003062617
 2560 N FAIR OAKS AVE N/A
 UNINCORPORATED, CA

HMS:

Facility Id: 006763-I06990
 Facility Type: I01
 Permit Number: 00010673C Permit Status: Permit
 Facility Status: Permit Area: 3
 Region: Los Angeles County:

32 NEW ERA CLEANERS RCRIS-SQG 1000857794
 2525 N LAKE AVE UNIT 6 FINDS CAD983672411
 ALTADENA, CA 91001 HAZNET
 CLEANERS

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

NEW ERA CLEANERS (Continued)

1000857794

RCRIS:

Owner: JAMES J KIM
 (818) 798-4213
 EPA ID: CAD983672411
 Contact: JAMES J KIM
 (818) 798-4213
 Classification: Small Quantity Generator
 Used Oil Recyc: No
 TSDF Activities: Not reported
 Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
 Facility Registry System (FRS)
 Resource Conservation and Recovery Act Information system (RCRAINFO)

CA Cleaners:

Create Date: 12/08/1995
 Inactive Date: 06/30/2000
 EPA Id: CAD983672411
 County : Los Angeles

HAZNET:

Gepaid: CAD983672411
 Tepaid: CAT000613893
 Gen County: Los Angeles
 Tsd County: Los Angeles
 Tons: .1375
 Category: Liquids with halogenated organic compounds > 1000 mg/l
 Disposal Method: Transfer Station
 Contact: JAMES J KIM
 Telephone: (626) 798-4213
 Mailing Address: 2525 LAKE AVE STE 7
 ALTADENA, CA 91001
 County Los Angeles
 Gepaid: CAD983672411
 Tepaid: CAT000613893
 Gen County: Los Angeles
 Tsd County: Los Angeles
 Tons: .0000
 Category:
 Disposal Method: Not reported
 Contact: JAMES J KIM
 Telephone: (626) 798-4213
 Mailing Address: 2525 LAKE AVE STE 7
 ALTADENA, CA 91001
 County Los Angeles

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

NEW ERA CLEANERS (Continued)

1000857794

Gepaid: CAD983672411
 Tepaid: CAT000613893
 Gen County: Los Angeles
 Tsd County: Los Angeles
 Tons: .5000
 Category: Liquids with halogenated organic compounds > 1000 mg/l
 Disposal Method: Transfer Station
 Contact: JAMES J KIM
 Telephone: (626) 798-4213
 Mailing Address: 2525 LAKE AVE STE 7
 ALTADENA, CA 91001
 County: Los Angeles

Gepaid: CAD983672411
 Tepaid: CAT000613893
 Gen County: Los Angeles
 Tsd County: Los Angeles
 Tons: .4575
 Category: Liquids with halogenated organic compounds > 1000 mg/l
 Disposal Method: Transfer Station
 Contact: JAMES J KIM
 Telephone: (626) 798-4213
 Mailing Address: 2525 LAKE AVE STE 7
 ALTADENA, CA 91001
 County: Los Angeles

Gepaid: CAD983672411
 Tepaid: CAT000613893
 Gen County: Los Angeles
 Tsd County: Los Angeles
 Tons: .2175
 Category: Halogenated solvents (chloroform, methyl chloride, perchloroethylene, etc.)
 Disposal Method: Transfer Station
 Contact: JAMES J KIM
 Telephone: (626) 798-4213
 Mailing Address: 2525 LAKE AVE STE 7
 ALTADENA, CA 91001
 County: Los Angeles

The CA HAZNET database contains 7 additional records for this site.
 Please contact your EDR Account Executive for more information.

33 **SAHAG MESROB ARMENIAN CHURCH**
2501 N MAIDEN LANE
ALTADENA, CA 91001

FINDS 1004444087
110011555245

FINDS:
 Other Pertinent Environmental Activity Identified at Site:
 Facility Registry System (FRS)
 National Compliance Database (NCDB)

33 **SAHAG MESROB ARMENIAN CHRISTIAN SCHOOL**
2501 N MAIDEN LANE
ALTADENA, CA 91001

FTTS 1006419063
N/A

FTTS:
 Case Number: Not reported
 Docket Number: 09-90-0038
 Complaint Issued: 07/31/199

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number
 EPA ID Number

Database(s)

SAHAG MESROB ARMENIAN CHRISTIAN SCHOOL (Continued)

1006419063

Complaint Closed: 03/06/1991
 Abatement Amount: 03/06/1991
 Proposed Penalty: 4000
 Final Assessment: 1500
 Final Order Date: 0
 Close Date: 03/06/1991
 Violation: AHERA LEA, Failure to Submit/Include/Update Management Plan

FCTS Insp:
 Region: 1006419063
 Inspected Date: AEA
 Insp Number: AEA
 Violation occurred: MANCUS
 Inspector: US
 Investigation Type: T
 Facility Function: 19900116R090540
 Investig Reason: Not reported
 Legislation Code: 09

34 **LA CO FD FIRE STA #011
 2521 N EL MOLINO AVE
 UNINCORPORATED, CA**

**LOS ANGELES CO. HMS S102058831
 N/A**

HMS:
 Facility Id: 012373-012504
 Facility Type: T0
 Permit Number: 00004249T
 Facility Status: Removed
 Region: Los Angeles County:
 Permit Status: Removed
 Area: 3

34 **FIRE STATION #11
 2521 EL MOLINO AVE
 ALTADENA, CA 91001**

**HIST UST U001566398
 N/A**

UST HIST:
 Facility ID: 20746
 Tank Num: 1
 Tank Capacity: 550
 Tank Used for: PRODUCT
 Type of Fuel: DIESEL
 Leak Detection: Stock Inventor
 Contact Name: L.A. COUNTY MECHANICAL DEPARTM
 Total Tanks: 4
 Facility Type: 2
 Container Num: #1
 Year Installed: Not reported
 Tank Construction: Not reported
 Telephone: (213) 267-2242
 Region: STATE
 Other Type: FIRE ST

Facility ID: 20746
 Tank Num: 2
 Tank Capacity: 1000
 Tank Used for: PRODUCT
 Type of Fuel: DIESEL
 Leak Detection: Stock Inventor
 Contact Name: L.A. COUNTY MECHANICAL DEPARTM
 Total Tanks: 4
 Facility Type: 2
 Container Num: #2
 Year Installed: Not reported
 Tank Construction: Not reported
 Telephone: (213) 267-2242
 Region: STATE
 Other Type: FIRE ST

Facility ID: 20746
 Tank Num: 3
 Tank Capacity: 1000
 Tank Used for: PRODUCT
 Container Num: #1
 Year Installed: Not reported

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number
 EPA ID Number

Database(s)

FIRE STATION #11 (Continued)

U001566398

Type of Fuel:	DIESEL	Tank Construction:	Not reported
Leak Detection:	Stock Inventor		
Contact Name:	L.A. COUNTY MECHANICAL DEPARTM	Telephone:	(213) 267-2242
Total Tanks:	4	Region:	STATE
Facility Type:	2	Other Type:	FIRE ST
Facility ID:	20746		
Tank Num:	4	Container Num:	#2
Tank Capacity:	1000	Year Installed:	Not reported
Tank Used for:	PRODUCT		
Type of Fuel:	DIESEL	Tank Construction:	Not reported
Leak Detection:	Stock Inventor		
Contact Name:	L.A. COUNTY MECHANICAL DEPARTM	Telephone:	(213) 267-2242
Total Tanks:	4	Region:	STATE
Facility Type:	2	Other Type:	FIRE ST

**34 LA COUNTY FIRE DEPT STATION 11
 2521 EL MOLINO AVE
 ALTADENA, CA 91001**

**AST A100215528
 N/A**

AST:
 Owner: LOS ANGELES COUNTY FIRE DEPT
 Total Gallons: 1000

**35 LOS ANGELES CO DEPT OF PUBLIC
 252 W MOUNTAIN VIEW ST
 ALTADENA, CA 91001**

**RCRIS-SQG 1000597197
 FINDS CAD983611989
 HAZNET**

RCRIS:
 Owner: LOS ANGELES COUNTY DEPT OF PUBLIC WORKS
 (818) 337-1277
 EPA ID: CAD983611989
 Contact: PHIL LATIOLATT
 (818) 337-1277
 Classification: Small Quantity Generator
 Used Oil Recyc: No
 TSDF Activities: Not reported
 Violation Status: No violations found

FINDS:
 Other Pertinent Environmental Activity Identified at Site:
 Facility Registry System (FRS)
 Resource Conservation and Recovery Act Information system (RCRAINFO)

HAZNET:
 Gepaid: CAD983611989
 Tepaid: CAT080022148
 Gen County: Los Angeles
 Tsd County: San Bernardino
 Tons: .0250
 Category: Laboratory waste chemicals
 Disposal Method: Not reported
 Contact: LOS ANGELES COUNTY DEPT OF PUB
 Telephone: (800) 675-4357
 Mailing Address: 14747 RAMONA BLVD # E
 BALDWIN PARK, CA 91706 - 3435
 County: Los Angeles

MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number
EPA ID Number

Database(s)

LOS ANGELES CO DEPT OF PUBLIC (Continued)

1000597197

Gepaid: CAD983611989
Tepaid: CAT080022148
Gen County: Los Angeles
Tsd County: San Bernardino
Tons: .0250
Category: Laboratory waste chemicals
Disposal Method: Transfer Station
Contact: LOS ANGELES COUNTY DEPT OF PUB
Telephone: (800) 675-4357
Mailing Address: 14747 RAMONA BLVD # E
BALDWIN PARK, CA 91706 - 3435
County Los Angeles

Gepaid: CAD983611989
Tepaid: CAT080011059
Gen County: Los Angeles
Tsd County: Los Angeles
Tons: .0000
Category:
Disposal Method: Not reported
Contact: LOS ANGELES COUNTY DEPT OF PUB
Telephone: (800) 675-4357
Mailing Address: 14747 RAMONA BLVD # E
BALDWIN PARK, CA 91706 - 3435
County Los Angeles

Gepaid: CAD983611989
Tepaid: CAT080011059
Gen County: Los Angeles
Tsd County: Los Angeles
Tons: .1250
Category: Off-specification, aged, or surplus organics
Disposal Method: Disposal, Other
Contact: LOS ANGELES COUNTY DEPT OF PUB
Telephone: (800) 675-4357
Mailing Address: 14747 RAMONA BLVD # E
BALDWIN PARK, CA 91706 - 3435
County Los Angeles

Gepaid: CAD983611989
Tepaid: CAT080013352
Gen County: Los Angeles
Tsd County: Los Angeles
Tons: 4.9206
Category: Oil/water separation sludge
Disposal Method: Recycler
Contact: LOS ANGELES COUNTY DEPT OF PUB
Telephone: (800) 675-4357
Mailing Address: 14747 RAMONA BLVD # E
BALDWIN PARK, CA 91706 - 3435
County Los Angeles

The CA HAZNET database contains 1 additional record for this site.
Please contact your EDR Account Executive for more information.

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number
 EPA ID Number

Database(s)

(Continued)

S105666572

CHMIRS:

OES Control Number:	00-3210	DOT ID:	Not reported
DOT Hazard Class:	Not Reported		
Chemical Name:	Hydraulic Oil		
Extent of Release:	Not reported		
CAS Number:	Not reported	Quantity Released:	50
Environmental Contamination:	None Reported	Property Use:	Not reported
Incident Date:	Not reported	Date Completed:	7/17/00
Time Completed :	Not reported		
Physical State Stored :	Not reported		
Physical State Released :	Not reported		
Release Unit :	Not reported		
Container Description :	Not reported		
Container Type :	Not reported		
Container Material :	Not reported		
Level Of Container :	Not reported		
Container Capacity :	Not reported		
Container Capacity Units (code) :	Not reported		
Extent Of Release (code) :	Not reported		
Agency Id Number :	Not reported		
Agency Incident Number :	Not reported		
OES Incident Number :	00-3210		
Time Notified :	Not reported		
Surrounding Area :	Not reported		
Estimated Temperature :	Not reported		
Property Management :	Not reported		
More Than Two Substances Involved? :	Not reported		
Special Studies 1 :	Not reported		
Special Studies 2 :	Not reported		
Special Studies 3 :	Not reported		
Special Studies 4 :	Not reported		
Special Studies 5 :	Not reported		
Special Studies 6 :	Not reported		
Responding Agency Personel # Of Injuries :	0		
Responding Agency Personel # Of Fatalities :	0		
Resp Agncy Personel # Of Decontaminated :	Not reported		
Others Number Of Decontaminated :	Not reported		
Others Number Of Injuries :	Not reported		
Others Number Of Fatalities :	Not reported		
Vehicle Make/year :	Not reported		
Vehicle License Number :	Not reported		
Vehicle State :	Not reported		
Vehicle Id Number :	Not reported		
CA/DOT/PUC/ICC Number :	Not reported		
Company Name :	Not reported		
Reporting Officer Name/ID :	Not reported		
Report Date :	Not reported		
Comments :	Not reported		
Facility Telephone Number :	Not reported		
Waterway Involved :	No		
Waterway :	Not reported		
Spill Site :	Other		
Cleanup By :	Reporting Party		
Containment :	Yes		
What Happened :	A pressure line corrodided leaking oil into the ground.		
Date/Time :	7/17/00 730		
Evacuations :	0		

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number
 Database(s) EPA ID Number

(Continued)

S105666572

Type : PETROLEUM
 Other : Not reported
 Chemical 1 : Not Reported
 Chemical 2 : Not Reported
 Chemical 3 : Not Reported

35

LA CO DPW FLEET MANAGEMENT
252 MOUNTAIN VIEW ST
ALTADENA, CA 91001

UST U003775841
 N/A

State UST:

Facility ID: 000645
 Total Tanks: 1
 Region: STATE
 Local Agency: 19000

UST San Francisco County:

Facility ID: 645
 Tank ID: Not reported
 Receive Date: 3/26/90
 Certified Date: Not reported
 Mailing Address: Not reported
 Care Of Address : Not reported
 Type Of Action : Not reported
 Local Tank Id : Not reported

Case Number: Not reported
 Owner Name: Not reported
 Close Date: Not reported

Number Of Tanks : 1
 Location Within Site: Not reported
 Tank Manufacturer: Not reported

Compartmentalized Tank : Not reported
 Date Tank Installed : Not reported
 Tank Capacity : Not reported
 # Of Tank Compartments : Not reported
 Additional Desc : Not reported
 Petroleum Type : Not reported
 Type Of Tank : Not reported
 Tank Material - Primary Tank : Not reported
 Tank Material - Secondary Tank : Not reported
 Tank Interior Lining/coating : Not reported
 Tank Int Lining Install Dt: Not reported
 Other Tank Corrosive Protection : Not reported
 Date Tank Corrosive Protection Install : Not reported
 Year Spill And Overfill Installed :

Tank Use : Not reported
 Common Name : Not reported

Spill Containment : Not reported
 Drop Tube : Not reported
 Striker Plate : Not reported

Type Of Spill Protection :
 Spill Containment : Not reported
 Drop Tube : Not reported
 Striker Plate : Not reported

Year Overfill Protection Equipment Installed :
 Alarm : Not reported
 Ball Float : Not reported
 Fill Tube Shut : Not reported
 Exempt : Not reported

Tank Leak Detection (Single Wall) :
 Visual (Exposed Portion) : Not reported
 Automatic Tank Gauging : Not reported
 Continuous Atg : Not reported
 Statscl Invntry Reconciliation & Biennial Tank Test : Not reported
 Manual Tank Gauging : Not reported
 Vadose Zone Tank Leak Detection : Not reported
 Groundwater : Not reported

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

LA CO DPW FLEET MANAGEMENT (Continued)

U003775841

Tank Testing :	Not reported
Other Detection :	Not reported
Tank Leak Detection (Double Wall) :	
Visual (Single Wall In Vault Only) :	Not reported
Continuous Interstitial Monitoring :	Not reported
Manual Monitoring :	Not reported
Estimated Date Last Used :	Not reported
Estimated Qty Of Substance Remaining :	Not reported
Tank Filled With Inert Material :	Not reported
Piping System Type (Underground) :	
Pressure :	Not reported
Suction :	Not reported
Gravity :	Not reported
Piping System Type (Aboveground) :	
Pressure :	Not reported
Suction :	Not reported
Gravity :	Not reported
Piping Construction (Underground) :	
Single Wall :	Not reported
Double Wall :	Not reported
Lined Trench :	Not reported
Unknown :	Not reported
Other :	Not reported
Piping Manufacturer (Underground) :	Not reported
Piping Construction (Aboveground) :	
Single Wall :	Not reported
Double Wall :	Not reported
Unknown :	Not reported
Other :	Not reported
Piping Manufacturer (Aboveground) :	Not reported
Piping Mat. And Corrosion Protection (Underground) :	
Bare Steel :	Not reported
Stainless Steel :	Not reported
Plastic Compatible With Contents :	Not reported
Fiberglass :	Not reported
Steel W/coating :	Not reported
FRP Compatible W/100% Methanol :	Not reported
Galvanized Steel :	Not reported
Flexible (HDPE - High Density Polyethylene) :	Not reported
Cathodic Protection :	Not reported
Unknown :	Not reported
Other :	Not reported
Piping Mat. & Corrosion Protec (Aboveground) :	
Bare Steel :	Not reported
Stainless Steel :	Not reported
Plastic Compatible With Contents :	Not reported
Fiberglass :	Not reported
Steel W/coating :	Not reported
Frp Compatible W/100% Methanol :	Not reported
Galvanized Steel :	Not reported
Flexible (HDPE - High Density Polyethylene) :	Not reported
Cathodic Protec :	Not reported
Unknown :	Not reported
Other :	Not reported
Piping Leak Detection (Underground - Single Wall) :	
Electronic Line Leak Detector/ Auto Shutoff/ Alarms :	Not reported
Monthly 0.2 Gph Test :	Not reported

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number
 Database(s) EPA ID Number

LA CO DPW FLEET MANAGEMENT (Continued)

U003775841

Annual Integrity Test :	Not reported
Daily Visual Monitrng ,Trienn Integrity Test :	Not reported
Self Monitoring :	Not reported
Biennial Integrity Test :	Not reported
Piping Leak Detection (Secondarily Contained) :	
Sump Sensor, Alarms ,Auto Shutoff For Leaks :	Not reported
Sump Snsr, Alrm ,Auto Shutoff For Leaks, Failure, & Disconnect :	Not reported
Sump Sensor ,Alarms ,No Auto Shutoff :	Not reported
Pressure, Auto Leak Detctr ,Flow Shutoff Or Restrctn	Not reported
Annual Integrity Test :	Not reported
Suction,Gravity ,Sump Sensor,Alarms :	Not reported
Piping Leak Detection (Emergency Generators) :	
Sump Sensor W/O Auto Shutoff /Alarms :	Not reported
Auto Leak Detector W/O Flow Shutoff Or Restrctn :	Not reported
Annual Integrity Test :	Not reported
Piping Leak Detectn Abovegrnd - Emrgncy Gen - Daily Visual Chk :	Not reported
Pipe Integrity Test, Underground :	Not reported
Piping Leak Detection (Aboveground - Single Wall) :	
Electronic Line Leak Detector /Auto Shutoff /Alarms :	Not reported
Monthly 0.2 Gph Test :	Not reported
Annual Integrity Test :	Not reported
Single Wall, Pressure Daily Visual Check :	Not reported
Single Wall, Suction - Daily Visual Monitoring :	Not reported
Triennial Integrity Test :	Not reported
Self Monitoring :	Not reported
Single Wall, Gravity - Daily Visual Monitoring :	Not reported
Biennial Integrity Test :	Not reported
Piping Leak Detection (Aboveground - Secondarily Contained)	
Sump Sensor, Alarms, Auto Shutoff For Leaks :	Not reported
Piping Leak Detection (Underground - Secondarily Contained)	
Sump Snsr, Alrm , Auto Shutoff For Leaks, Failre & Disconct :	Not reported
Sump Sensor, Alarms, No Auto Shutoff :	Not reported
Pressure - Auto Leak Detctr, Flow Shutoff /Restrctn :	Not reported
Annual Integrity Test :	Not reported
Suction/gravity - Sump Sensor , Alarms :	Not reported
Piping Leak Detection Underground (Emergency Generators)	
Sump Sensor Without Auto Shutoff , Alarms :	Not reported
Auto Leak Detector W/o Flow Shutoff Or Restrctn :	Not reported
Annual Integrity Test :	Not reported
Daily Visual Check :	Not reported
Pipe Integrity Test, Aboveground :	Not reported
Date Dispenser Containment Installed :	Not reported
Dispenser Containment Type :	Not reported
Date Certified (Tank Unit) :	Not reported
Owner/ Operator Name (Tank Unit) :	Not reported
Owner/ Operator Title (Tank Unit) :	Not reported
Permit Number :	Not reported
Permit Approved By :	Not reported
Permit Expiration Date :	Not reported
Last Annual Monitoring Cert:	Not reported
Secondary Containment Test :	Not reported
Spill Containment Present :	Not reported
Drop Tube Present :	Not reported
Striker Plate Present :	Not reported
Alarm Present :	Not reported
Ball Float Present :	Not reported
Fill Tube Present :	Not reported

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number
 EPA ID Number

Database(s)

LA CO DPW FLEET MANAGEMENT (Continued)

U003775841

Other Tank Leak Detection Present : Not reported

**35 MAINTENANCE DISTRICT #2
 252 MOUNTAIN VIEW ST
 ALTADENA, CA 91001**

**HIST UST U001566404
 N/A**

UST HIST:

Facility ID:	33878	Container Num:	WH2-UG
Tank Num:	1	Year Installed:	Not reported
Tank Capacity:	1000	Tank Construction:	3/16 inches
Tank Used for:	PRODUCT	Telephone:	(213) 798-1178
Type of Fuel:	UNLEADED	Region:	STATE
Leak Detection:	Stock Inventor	Other Type:	COUNTY GOVERNMENT
Contact Name:	BILL JONAS		
Total Tanks:	3		
Facility Type:	2		

Facility ID:	33878	Container Num:	WH2-RG
Tank Num:	2	Year Installed:	Not reported
Tank Capacity:	1000	Tank Construction:	3/16 inches
Tank Used for:	PRODUCT	Telephone:	(213) 798-1178
Type of Fuel:	REGULAR	Region:	STATE
Leak Detection:	Stock Inventor	Other Type:	COUNTY GOVERNMENT
Contact Name:	BILL JONAS		
Total Tanks:	3		
Facility Type:	2		

Facility ID:	33878	Container Num:	WH2-WO
Tank Num:	3	Year Installed:	Not reported
Tank Capacity:	300	Tank Construction:	3/16 inches
Tank Used for:	WASTE	Telephone:	(213) 798-1178
Type of Fuel:	WASTE OIL	Region:	STATE
Leak Detection:	Stock Inventor	Other Type:	COUNTY GOVERNMENT
Contact Name:	BILL JONAS		
Total Tanks:	3		
Facility Type:	2		

**35 CNTY OF L A PUBLIC WORKS
 252 W MOUNTAIN VIEW ST
 ALTADENA, CA 91001**

**HAZNET S103646559
 N/A**

HAZNET:

Gepaid:	CAL000009803
Tepaid:	CAT080013352
Gen County:	Los Angeles
Tsd County:	Los Angeles
Tons:	.4587
Category:	Unspecified aqueous solution
Disposal Method:	Not reported
Contact:	LA COUNTY DEPARTMENT OF PUBLIC
Telephone:	(626) 794-7732
Mailing Address:	252 MOUNTAIN VIEW ST # W ALTADENA, CA 91001 - 5016
County:	Los Angeles

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

CNTY OF L A PUBLIC WORKS (Continued)

S103646559

Gepaid: CAL000009803
 Tepaid: CAD000088252
 Gen County: Los Angeles
 Tsd County: Los Angeles
 Tons: .6255
 Category: Waste oil and mixed oil
 Disposal Method: Transfer Station
 Contact: LA COUNTY DEPARTMENT OF PUBLIC
 Telephone: (626) 794-7732
 Mailing Address: 252 MOUNTAIN VIEW ST # W
 ALTADENA, CA 91001 - 5016
 County Los Angeles

Gepaid: CAL000009803
 Tepaid: CAD028409019
 Gen County: Los Angeles
 Tsd County: Los Angeles
 Tons: .4170
 Category: Waste oil and mixed oil
 Disposal Method: Transfer Station
 Contact: LA COUNTY DEPARTMENT OF PUBLIC
 Telephone: (626) 794-7732
 Mailing Address: 252 MOUNTAIN VIEW ST # W
 ALTADENA, CA 91001 - 5016
 County Los Angeles

Gepaid: CAL000009803
 Tepaid: CAD028409019
 Gen County: Los Angeles
 Tsd County: Los Angeles
 Tons: .2000
 Category: Unspecified oil-containing waste
 Disposal Method: Transfer Station
 Contact: LA COUNTY DEPARTMENT OF PUBLIC
 Telephone: (626) 794-7732
 Mailing Address: 252 MOUNTAIN VIEW ST # W
 ALTADENA, CA 91001 - 5016
 County Los Angeles

Gepaid: CAL000009803
 Tepaid: CAD028409019
 Gen County: Los Angeles
 Tsd County: Los Angeles
 Tons: .6255
 Category: Waste oil and mixed oil
 Disposal Method: Transfer Station
 Contact: LA COUNTY DEPARTMENT OF PUBLIC
 Telephone: (626) 794-7732
 Mailing Address: 252 MOUNTAIN VIEW ST # W
 ALTADENA, CA 91001 - 5016
 County Los Angeles

The CA HAZNET database contains 15 additional records for this site.
 Please contact your EDR Account Executive for more information.

35

**LA CO DPW FLEET MGMT GROUP
 252 W MOUNTAIN VIEW ST
 UNINCORPORATED, CA**

**LOS ANGELES CO. HMS U003057063
 N/A**

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number
 EPA ID Number

Database(s)

LA CO DPW FLEET MGMT GROUP (Continued)

U003057063

HMS:

Facility Id:	000641-100645	Permit Status:	Closed
Facility Type:	I01	Area:	3
Permit Number:	000132858		
Facility Status:	Permit		
Region:	Los Angeles County:		

35

**LA CO DPW FLEET MANAGEMENT
 252 W MOUNTAIN VIEW ST
 UNINCORPORATED, CA**

SWF/LF S100614827
 LOS ANGELES CO. HMS N/A

LF:

Facility ID:	19-AA-0298
Operator:	Los Angeles Co Public Works Road M. Div
Operator Phone:	(626) 458-4183
Operator Addr:	900 S. Freemont Ave. Alhambra, CA 91803
Owner:	Not reported
Owner Address:	Not reported
	Not reported
Owner Telephone:	Not reported
Activity:	Solid Waste Disposal Site
Operator's Status:	Closed
Regulation Status:	To Be Determined
Region:	STATE
Lat/Long:	34.18333 / -118.13333
Permit Date:	Not reported
Accepted Waste:	
Restrictions:	
Status :	Not reported
Swisnumber :	Not reported
Site Type :	Not reported
Aka :	Not reported
Type Of Waste :	Not reported
Disposal Area :	Not reported
SWFP Date :	Not reported
WDR Number :	Not reported
Dates Of Operation :	Not reported
Closure Approved :	Not reported
Date Of Field Units :	Not reported
Surface Condition :	Not reported
Landfill Gas :	Not reported
Leachate :	Not reported
Emergency Response :	Not reported
Other Recommendation :	Not reported
Reassess Site :	Not reported
Priority For Site Assessment :	Not reported
Lea Date :	Not reported
Explanation:	Not Reported
No Further Action:	Not Reported
Permitted Throughput with Units:	0
Permitted Throughput with Units:	0
Permitted Throughput with Units:	0
Actual Throughput with Units:	Not reported
Actual Capacity with Units:	0
Permitted Capacity with Units:	0
Remaining Capacity with Units:	Not reported
Permitted Total Acreage:	0

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number
 EPA ID Number

Database(s)

LA CO DPW FLEET MANAGEMENT (Continued)

S100614827

Inspection Frequency: Quarterly
 Landuse Name: Not reported
 GIS Source: Place
 Permit Status: Not reported
 Category: Disposal
 Unit Number: 01
 Last Waste Tire Inspection Count : 0
 Last Waste Tire Inspection Date: 0
 Original Waste Tire Count: Not reported
 Original Waste Tire Count Date: Not reported
 Closure Date: / /
 Closure Type: Not reported
 Disposal Acreage: 0
 Remaining Capacity: 0

HMS:

Facility Id: 008969-000645
 Facility Type: T0
 Permit Number: 00001493T
 Facility Status: Permit
 Region: Los Angeles County

Permit Status: Removed
 Area: 3

36

**VACANT
 2501 N FAIR OAKS AVE
 UNINCORPORATED, CA**

**LOS ANGELES CO. HMS U003061742
 N/A**

HMS:

Facility Id: 005733-105943
 Facility Type: Not reported
 Permit Number: Not reported
 Facility Status: OPEN
 Region: Los Angeles County

Permit Status: Not reported
 Area: 3

36

**TETRA TECH INC
 2501 N FAIR OAKS AVE
 UNINCORPORATED, CA**

**LOS ANGELES CO. HMS S102058816
 N/A**

HMS:

Facility Id: 005733-005943
 Facility Type: Not reported
 Permit Number: Not reported
 Facility Status: OPEN
 Region: Los Angeles County

Permit Status: Not reported
 Area: 3

37

**MERIT CLEANERS
 841 E MARIPOSA
 ALTADENA, CA 91001**

**RCRIS-SQG 1000263640
 FINDS CAD982036089
 HAZNET
 CLEANERS**

MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number
EPA ID Number

Database(s)

MERIT CLEANERS (Continued)

1000263640

RCRIS:

Owner: DAVID RICHARDSON
(415) 555-1212
EPA ID: CAD982036089
Contact: ENVIRONMENTAL MANAGER
Classification: Small Quantity Generator
Used Oil Recyc: No
TSDf Activities: Not reported
Violation Status: Violations exist
Regulation Violated: 262.10-12.A
Area of Violation: GENERATOR-ALL REQUIREMENTS (OVERSIGHT)
Date Violation Determined: 03/11/1992
Actual Date Achieved Compliance: 03/11/1997

There are 1 violation record(s) reported at this site:

<u>Evaluation</u>	<u>Area of Violation</u>	<u>Date of Compliance</u>
Compliance Evaluation Inspection	GENERATOR-ALL REQUIREMENTS (OVERSIGHT)	19970311

FINDS:

Other Pertinent Environmental Activity Identified at Site:
Facility Registry System (FRS)
Resource Conservation and Recovery Act Information system (RCRAINFO)

CA Cleaners:

Create Date: 03/01/1988
Inactive Date: 06/30/1998
EPA Id: CAD982036089
County : Los Angeles

HAZNET:

Gepaid: CAD982036089
Tepaid: CAT000613893
Gen County: Los Angeles
Tsd County: Los Angeles
Tons: .3150
Category: Liquids with halogenated organic compounds > 1000 mg/l
Disposal Method: Transfer Station
Contact: Not reported
Telephone: (000) 000-0000
Mailing Address: 841 E MARIPOSA ST
ALTADENA, CA 91001 - 2420
County: Los Angeles
Gepaid: CAD982036089
Tepaid: CAT000613893
Gen County: Los Angeles
Tsd County: Los Angeles
Tons: .0000
Category: Liquids with halogenated organic compounds > 1000 mg/l
Disposal Method: Not reported
Contact: Not reported
Telephone: (000) 000-0000
Mailing Address: 841 E MARIPOSA ST
ALTADENA, CA 91001 - 2420
County: Los Angeles



MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number
 EPA ID Number

Database(s)

MERIT CLEANERS (Continued)

1000263640

Gepaid: CAD982036089
 Tepaid: CAT000613893
 Gen County: Los Angeles
 Tsd County: Los Angeles
 Tons: .0600
 Category: Liquids with halogenated organic compounds > 1000 mg/l
 Disposal Method: Transfer Station
 Contact: Not reported
 Telephone: (000) 000-0000
 Mailing Address: 841 E MARIPOSA ST
 ALTADENA, CA 91001 - 2420
 County: Los Angeles

Gepaid: CAD982036089
 Tepaid: CAT000613893
 Gen County: Los Angeles
 Tsd County: Los Angeles
 Tons: .1000
 Category: Liquids with halogenated organic compounds > 1000 mg/l
 Disposal Method: Transfer Station
 Contact: Not reported
 Telephone: (000) 000-0000
 Mailing Address: 841 E MARIPOSA ST
 ALTADENA, CA 91001 - 2420
 County: Los Angeles

Gepaid: CAD982036089
 Tepaid: CAD981397417
 Gen County: Los Angeles
 Tsd County: Los Angeles
 Tons: .0000
 Category:
 Disposal Method: Recycler
 Contact: Not reported
 Telephone: (000) 000-0000
 Mailing Address: 841 E MARIPOSA ST
 ALTADENA, CA 91001 - 2420
 County: Los Angeles

The CA HAZNET database contains 11 additional records for this site.
 Please contact your EDR Account Executive for more information.

38 **OLD CHEVRON STA** **LOS ANGELES CO. HMS** **S102058773**
 2445 N LINCOLN AVE **N/A**
 UNINCORPORATED, CA

HMS:
 Facility Id: 016092-020991
 Facility Type: Not reported
 Permit Number: Not reported Permit Status: Not reported
 Facility Status: OPEN Area: 3
 Region: Los Angeles County:

38 **J LEE HARTMAN** **HAZNET** **S103971288**
 2439-5 LINCOLN AVE **N/A**
 ALTADENA, CA 91001

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

J LEE HARTMAN (Continued)

S103971288

HAZNET:
 Gepaid: CAC000761312
 Tepaid: CAT080013352
 Gen County: Los Angeles
 Tsd County: Los Angeles
 Tons: 5.8380
 Category: Tank bottom waste
 Disposal Method: Recycler
 Contact: J LEE HARTMAN
 Telephone: (000) 000-0000
 Mailing Address: 8033 SUNSET BLVD, #200
 LOS ANGELES, CA 90046
 County: Los Angeles

38

**ALLIANCE AUTOMOTIVE
 2445 NORTH LINCOLN AVE.
 ALTADENA, CA 91001**

**HAZNET S103645620
 N/A**

HAZNET:
 Gepaid: CAL000108185
 Tepaid: CAT080013352
 Gen County: Los Angeles
 Tsd County: Los Angeles
 Tons: 2.2935
 Category: Oil/water separation sludge
 Disposal Method: Recycler
 Contact: DAVID OWENS
 Telephone: (818) 794-8660
 Mailing Address: 2445 LINCOLN AVE
 ALTADENA, CA 91001 - 5265
 County: Los Angeles

Gepaid: CAL000108185
 Tepaid: CAD981696420
 Gen County: Los Angeles
 Tsd County: Los Angeles
 Tons: .0417
 Category: Waste oil and mixed oil
 Disposal Method: Transfer Station
 Contact: DAVID OWENS
 Telephone: (818) 794-8660
 Mailing Address: 2445 LINCOLN AVE
 ALTADENA, CA 91001 - 5265
 County: Los Angeles

39

**COLD TYPE
 848 EAST MARCHETA STREET
 ALTADENA, CA 91001**

**HAZNET S103674166
 N/A**

HAZNET:
 Gepaid: CAL913235896
 Tepaid: CAD982524613
 Gen County: Los Angeles
 Tsd County: Orange
 Tons: .7213
 Category: Photochemicals/photoprocessing waste
 Disposal Method: Recycler
 Contact: DOUG KAHN



MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

COLD TYPE (Continued)

S103674166

Telephone: (818) 798-7581
 Mailing Address: 848 E MARCHUTA ST
 ALTADENA, CA 91001
 County Los Angeles
 Gepaid: CAL913235896
 Tepaid: CAD982524613
 Gen County: Los Angeles
 Tsd County: Orange
 Tons: .1251
 Category: Photochemicals/photoprocessing waste
 Disposal Method: Not reported
 Contact: DOUG KAHN
 Telephone: (818) 798-7581
 Mailing Address: 848 E MARCHUTA ST
 ALTADENA, CA 91001
 County Los Angeles
 Gepaid: CAL913235896
 Tepaid: CAD982524613
 Gen County: Los Angeles
 Tsd County: Orange
 Tons: .6838
 Category: Photochemicals/photoprocessing waste
 Disposal Method: Recycler
 Contact: DOUG KAHN
 Telephone: (818) 798-7581
 Mailing Address: 848 E MARCHUTA ST
 ALTADENA, CA 91001
 County Los Angeles

40

PASADENA CEMETERY ASSO
2400 N FAIR OAKS AVE
ALTADENA, CA 91001

HAZNET S102058718
LOS ANGELES CO. HMS N/A

HAZNET:
 Gepaid: CAL000072959
 Tepaid: CAT000613893
 Gen County: Los Angeles
 Tsd County: Los Angeles
 Tons: 0.0625
 Category: Aqueous solution with less than 10% total organic residues
 Disposal Method: Transfer Station
 Contact: PASADENA CEMETERY ASSOC
 Telephone: (626) 794-7133
 Mailing Address: PO BOX 6069
 ALTADENA, CA 91003 - 6069
 County Los Angeles

HMS:
 Facility Id: 009352-009155
 Facility Type: T0
 Permit Number: 00000138T
 Facility Status: Permit
 Region: Los Angeles County
 Permit Status: Permit
 Area: 3

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number
 Database(s) EPA ID Number

40 MOUNTAIN VIEW CEMETERY **HIST UST** **U001566407**
2400 FAIR OAKS AVE **N/A**
ALTADENA, CA 91001

UST HIST:

Facility ID:	63656	Container Num:	1
Tank Num:	1	Year Installed:	Not reported
Tank Capacity:	5000	Tank Construction:	Not reported
Tank Used for:	PRODUCT	Telephone:	(818) 794-7133
Type of Fuel:	PREMIUM	Region:	STATE
Leak Detection:	Stock Inventor	Other Type:	CEMETERY
Contact Name:	GERALD NASH		
Total Tanks:	6		
Facility Type:	2		

Facility ID:	63656	Container Num:	2
Tank Num:	2	Year Installed:	Not reported
Tank Capacity:	5000	Tank Construction:	Not reported
Tank Used for:	PRODUCT	Telephone:	(818) 794-7133
Type of Fuel:	REGULAR	Region:	STATE
Leak Detection:	Stock Inventor	Other Type:	CEMETERY
Contact Name:	GERALD NASH		
Total Tanks:	6		
Facility Type:	2		

Facility ID:	63656	Container Num:	3
Tank Num:	3	Year Installed:	Not reported
Tank Capacity:	5000	Tank Construction:	Not reported
Tank Used for:	PRODUCT	Telephone:	(818) 794-7133
Type of Fuel:	UNLEADED	Region:	STATE
Leak Detection:	Stock Inventor	Other Type:	CEMETERY
Contact Name:	GERALD NASH		
Total Tanks:	6		
Facility Type:	2		

Facility ID:	63656	Container Num:	4
Tank Num:	4	Year Installed:	1982
Tank Capacity:	1000	Tank Construction:	10 gauge
Tank Used for:	PRODUCT	Telephone:	(818) 794-7133
Type of Fuel:	DIESEL	Region:	STATE
Leak Detection:	Stock Inventor	Other Type:	CEMETERY
Contact Name:	GERALD NASH		
Total Tanks:	6		
Facility Type:	2		

Facility ID:	63656	Container Num:	5
Tank Num:	5	Year Installed:	Not reported
Tank Capacity:	500	Tank Construction:	Not reported
Tank Used for:	WASTE	Telephone:	(818) 794-7133
Type of Fuel:	WASTE OIL	Region:	STATE
Leak Detection:	Stock Inventor	Other Type:	CEMETERY
Contact Name:	GERALD NASH		
Total Tanks:	6		
Facility Type:	2		

Facility ID:	63656	Container Num:	6
Tank Num:	6	Year Installed:	Not reported
Tank Capacity:	550		
Tank Used for:	PRODUCT		

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number
 Database(s) EPA ID Number

MOUNTAIN VIEW CEMETERY (Continued)

U001566407

Type of Fuel:	Not Reported	Tank Construction:	Not reported
Leak Detection:	None		
Contact Name:	GERALD NASH	Telephone:	(818) 794-7133
Total Tanks:	6	Region:	STATE
Facility Type:	2	Other Type:	CEMETERY

**40 PASADENA CEMETERY ASSOCIATION
 2400 FAIR OAKS AVE
 ALTADENA, CA 91001**

**UST U003776250
 N/A**

State UST:
 Facility ID: 009155
 Total Tanks: 1
 Region: STATE
 Local Agency: 19000

**40 INTERNATIONAL BIORESEARCH SOLUTIONS
 2400 N FAIR OAKS AVE
 ALTADENA, CA 91007**

**HAZNET S104583359
 N/A**

HAZNET:
 Gepaid: CAL000214758
 Tepaid: AZR000035840
 Gen County: Los Angeles
 Tsd County: 0
 Tons: 0.0125
 Category: Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
 Disposal Method: Not reported
 Contact: INTERNTL BIO-RESCH SOLUTIONS
 Telephone: (800) 227-0054
 Mailing Address: 120 S HOUGHTON STE 138
 TUSAN, AZ 85748
 County: Los Angeles
 Gepaid: CAL000214758
 Tepaid: AZR000035840
 Gen County: Los Angeles
 Tsd County: 0
 Tons: 0.0625
 Category: Unspecified solvent mixture Waste
 Disposal Method: Not reported
 Contact: INTERNTL BIO-RESCH SOLUTIONS
 Telephone: (800) 227-0054
 Mailing Address: 120 S HOUGHTON STE 138
 TUSAN, AZ 85748
 County: Los Angeles

**41 THEOSOPHICAL UNIVERSITY PRESS
 2416 NORTH LAKE ST.
 ALTADENA, CA 91001**

**HAZNET S103991168
 N/A**

MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number
EPA ID Number

Database(s)

THEOSOPHICAL UNIVERSITY PRESS (Continued)

S103991168

HAZNET:

Gepaid: CAL000112988
Tepaid: CAT000613976
Gen County: Los Angeles
Tsd County: Orange
Tons: .0625
Category: Photochemicals/photoprocessing waste
Disposal Method: Transfer Station
Contact: THEOSOPHICAL ENDOWMENT CORP
Telephone: (000) 000-0000
Mailing Address: PO BOX C
PASADENA, CA 91109
County: Los Angeles

Gepaid: CAL000112988
Tepaid: CAD093459485
Gen County: Los Angeles
Tsd County: Fresno
Tons: .0667
Category: Photochemicals/photoprocessing waste
Disposal Method: Recycler
Contact: THEOSOPHICAL ENDOWMENT CORP
Telephone: (000) 000-0000
Mailing Address: PO BOX C
PASADENA, CA 91109
County: Los Angeles

Gepaid: CAL000112988
Tepaid: CAD981402522
Gen County: Los Angeles
Tsd County: Kern
Tons: .1668
Category: Photochemicals/photoprocessing waste
Disposal Method: Not reported
Contact: THEOSOPHICAL ENDOWMENT CORP
Telephone: (000) 000-0000
Mailing Address: PO BOX C
PASADENA, CA 91109
County: Los Angeles

Gepaid: CAL000112988
Tepaid: CAD099452708
Gen County: Los Angeles
Tsd County: Los Angeles
Tons: 0.2293
Category: Unspecified organic liquid mixture
Disposal Method: Not reported
Contact: THEOSOPHICAL ENDOWMENT CORP
Telephone: (000) 000-0000
Mailing Address: PO BOX C
PASADENA, CA 91109
County: Los Angeles

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number
 Database(s) EPA ID Number

THEOSOPHICAL UNIVERSITY PRESS (Continued)

S103991168

Gepaid: CAL000112988
 Tepaid: CAD093459485
 Gen County: Los Angeles
 Tsd County: Fresno
 Tons: 0.06
 Category: Photochemicals/photoprocessing waste
 Disposal Method: Recycler
 Contact: WILL THACKARA/MANAGER
 Telephone: (818) 798-3378
 Mailing Address: PO BOX C
 PASADENA, CA 91109
 County: Los Angeles

**41 PASADENA MEDIA INC
 2396 N LAKE ST
 UNINCORPORATED, CA**

**LOS ANGELES CO. HMS U003063174
 N/A**

HMS:
 Facility Id: 007400-107763
 Facility Type: I01
 Permit Number: 000009294
 Facility Status: Closed
 Region: Los Angeles County

Permit Status: Closed
 Area: 3

**42 292 N. FIGUEROA DR.
 ALTADENA, CA 0**

**CHMIRS S105655112
 N/A**

CHMIRS:
 OES Control Number: 98-3440 DOT ID: Not reported
 DOT Hazard Class: Not Reported
 Chemical Name: Muriatic Acid
 Extent of Release: Not reported
 CAS Number: Not reported Quantity Released: 1
 Environmental Contamination: None Reported Property Use: Not reported
 Incident Date: Not reported Date Completed: 7/29/98
 Time Completed : Not reported
 Physical State Stored : Not reported
 Physical State Released : Not reported
 Release Unit : Not reported
 Container Description : Not reported
 Container Type : Not reported
 Container Material : Not reported
 Level Of Container : Not reported
 Container Capacity : Not reported
 Container Capacity Units (code) : Not reported
 Extent Of Release (code) : Not reported
 Agency Id Number : Not reported
 Agency Incident Number : Not reported
 OES Incident Number : 98-3440
 Time Notified : Not reported
 Surrounding Area : Not reported
 Estimated Temperature : Not reported
 Property Management : Not reported
 More Than Two Substances Involved? : Not reported
 Special Studies 1 : Not reported
 Special Studies 2 : Not reported
 Special Studies 3 : Not reported

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number
 Database(s) EPA ID Number

(Continued)

S105655112

Special Studies 4 :	Not reported
Special Studies 5 :	Not reported
Special Studies 6 :	Not reported
Responding Agency Personel # Of Injuries :	0
Responding Agency Personel # Of Fatalities :	0
Resp Agency Personel # Of Decontaminated :	Not reported
Others Number Of Decontaminated :	Not reported
Others Number Of Injuries :	Not reported
Others Number Of Fatalities :	Not reported
Vehicle Make/year :	Not reported
Vehicle License Number :	Not reported
Vehicle State :	Not reported
Vehicle Id Number :	Not reported
CA/DOT/PUC/ICC Number :	Not reported
Company Name :	Not reported
Reporting Officer Name/ID :	Not reported
Report Date :	Not reported
Comments :	Not reported
Facility Telephone Number :	Not reported
Waterway Involved :	Unknown
Waterway :	Not reported
Spill Site :	Residence
Cleanup By :	Hazmat
Containment :	No
What Happened :	At a private residence. One gallon spilled onto driveway and formed a cloud. 30 residents evacuated but none transported to hospital. Command Post set up nearby and Red Cross is enroute. Battalion Chief Scott on scene can provide further details re: t
Date/Time :	7/29/98 914
Evacuations :	30
Type :	CHEMICAL
Other :	Not reported
Chemical 1 :	Not Reported
Chemical 2 :	Not Reported
Chemical 3 :	Not Reported

43

1X RUBIO CANYON LAND & WATER ASSOCIATION
263 W FIGUEROA ST
ALTADENA, CA 91006

HAZNET S103947625
N/A

HAZNET:

Gepaid:	CAC000138893
Tepaid:	CAT080013352
Gen County:	Los Angeles
Tsd County:	Los Angeles
Tons:	1.8348
Category:	Aqueous solution with less than 10% total organic residues
Disposal Method:	Recycler
Contact:	ASSOCIATION
Telephone:	(000) 000-0000
Mailing Address:	583 E SACRAMENTO ST
	ALTADENO, CA 91006
County	Los Angeles

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)	Site	Database(s)	EPA ID Number

44	COASTAL CREMATION 2400 N FAIR OAKS AVE UNINCORPORATED, CA	LOS ANGELES CO. HMS	S102058719 N/A
-----------	--	----------------------------	---------------------------------

HMS:

Facility Id:	009352-009260		
Facility Type:	Not reported	Permit Status:	Not reported
Permit Number:	Not reported	Area:	3
Facility Status:	Removed		
Region:	Los Angeles County:		

45	LA CANADA HIGH SCHOOL 4463 OAK GROVE DRIVE LA CANADA, CA 91011	HAZNET	1000167859 N/A
-----------	---	---------------	---------------------------------

HAZNET:

Gepaid:	CAD982328379		
Tepaid:	CAL000027741		
Gen County:	Los Angeles		
Tsd County:	5		
Tons:	1.6856		
Category:	Asbestos-containing waste		
Disposal Method:	Disposal, Land Fill		
Contact:	HIGH SCHOOL		
Telephone:	(000) 000-0000		
Mailing Address:	5039 PALM DR		
	LA CANADA, CA 91011 - 3738		
County	Los Angeles		
Gepaid:	CAD982328379		
Tepaid:	CAT080022148		
Gen County:	Los Angeles		
Tsd County:	San Bernardino		
Tons:	.3127		
Category:	Laboratory waste chemicals		
Disposal Method:	Transfer Station		
Contact:	HIGH SCHOOL		
Telephone:	(000) 000-0000		
Mailing Address:	5039 PALM DR		
	LA CANADA, CA 91011 - 3738		
County	Los Angeles		

46	SIDS AUTO REPAIR 2315 N FAIROAKS AVE ALTADENA, CA 91001	HAZNET CA FID UST LOS ANGELES CO. HMS	S101586388 N/A
-----------	--	--	---------------------------------

HAZNET:

Gepaid:	CAL912353068		
Tepaid:	CAT000613893		
Gen County:	Los Angeles		
Tsd County:	Los Angeles		
Tons:	0.0958		
Category:	Aqueous solution with less than 10% total organic residues		
Disposal Method:	Transfer Station		
Contact:	ARELLAN ISIDRO/DEBORAH		
Telephone:	(626) 791-4730		
Mailing Address:	2315 FAIR OAKS AVE		
	ALTADENA, CA 91001		
County	Los Angeles		

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number
 EPA ID Number

Database(s)

SIDS AUTO REPAIR (Continued)

S101586388

FID:

Facility ID:	19048394	Regulate ID:	CAC000619
Reg By:	Inactive Underground Storage Tank Location	SIC Code:	Not reported
Cortese Code:	Not reported	Facility Tel:	(818) 794-8996
Status:	Inactive		
Mail To:	Not reported		
	2315 N FAIROAKS AVE		
	ALTADENA, CA 91001		
Contact:	Not reported	Contact Tel:	Not reported
DUNs No:	Not reported	NPDES No:	Not reported
Creation:	10/22/93	Modified:	00/00/00
EPA ID:	Not reported		
Comments:	Not reported		

Facility ID:	19048394	Regulate ID:	CAC000619
Reg By:	Active Underground Storage Tank Location	SIC Code:	Not reported
Cortese Code:	Not reported	Facility Tel:	(415) 697-7100
Status:	Active		
Mail To:	Not reported		
	124 STONEHEDGE RD		
	HILLSBOROUGH, CA 94404		
Contact:	Not reported	Contact Tel:	Not reported
DUNs No:	Not reported	NPDES No:	Not reported
Creation:	10/22/93	Modified:	00/00/00
EPA ID:	Not reported		
Comments:	Not reported		

HMS:

Facility Id:	015315-016494	Permit Status:	Removed
Facility Type:	T0	Area:	3
Permit Number:	00006156T		
Facility Status:	Removed		
Region:	Los Angeles County:		

47

ALTADENA 5 MIN CAR WASH
 2340 N LAKE AVE
 UNINCORPORATED, CA

LOS ANGELES CO. HMS U003059524
 N/A

HMS:

Facility Id:	003230-103344	Permit Status:	Closed
Facility Type:	I00	Area:	3
Permit Number:	000001406		
Facility Status:	Closed		
Region:	Los Angeles County:		

48

PARAMOUNT CLEANERS
 2345 LINCOLN AVE
 ALTADENA, CA 91001

RCRIS-SQG 1000149978
 FINDS CAD981636640
 CLEANERS

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number
 EPA ID Number

Database(s)

PARAMOUNT CLEANERS (Continued)

1000149978

RCRIS:

Owner: JOYCE STARR
 (415) 555-1212
 EPA ID: CAD981636640
 Contact: ENVIRONMENTAL MANAGER
 (818) 797-3355

Classification: Small Quantity Generator
 Used Oil Recyc: No
 TSD Activities: Not reported
 Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
 Facility Registry System (FRS)
 Resource Conservation and Recovery Act Information system (RCRAINFO)

CA Cleaners:

Create Date: 04/10/1987
 Inactive Date: 06/30/1996
 EPA Id: CAD981636640
 County : Los Angeles

49

FOOTHILLS MOVING CENTER
2320 LINCOLN AVE
ALTADENA, CA 91724

HIST UST U001569262
 N/A

UST HIST:

Facility ID:	3502		
Tank Num:	1	Container Num:	1
Tank Capacity:	9950	Year Installed:	1981
Tank Used for:	PRODUCT		
Type of Fuel:	REGULAR	Tank Construction:	1/4 inches
Leak Detection:	Stock Inventor, None		
Contact Name:	Not reported	Telephone:	(213) 791-0952
Total Tanks:	2	Region:	STATE
Facility Type:	2	Other Type:	Not reported

Facility ID:	3502		
Tank Num:	2	Container Num:	2
Tank Capacity:	5000	Year Installed:	1981
Tank Used for:	PRODUCT		
Type of Fuel:	UNLEADED	Tank Construction:	1/4 inches
Leak Detection:	Stock Inventor, None		
Contact Name:	Not reported	Telephone:	(213) 791-0952
Total Tanks:	2	Region:	STATE
Facility Type:	2	Other Type:	Not reported

49

U HAUL FOOTHILL 713 42
2320 N LINCOLN BLVD
ALTADENA, CA 91001

HAZNET S103992927
 N/A

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number
 EPA ID Number

Database(s)

U HAUL FOOTHILL 713 42 (Continued)

S103992927

HAZNET:

Gepaid: CAD981641657
 Tepad: CAT080013352
 Gen County: Los Angeles
 Tsd County: Los Angeles
 Tons: 1.6680
 Category: Tank bottom waste
 Disposal Method: Recycler
 Contact: Not reported
 Telephone: (000) 000-0000
 Mailing Address: 2320 N LINCOLN BLVD
 ALTADENA, CA 91001
 County: Los Angeles

Gepaid: CAD981641657
 Tepad: Not reported
 Gen County: Los Angeles
 Tsd County: 0
 Tons: .6255
 Category: Aqueous solution with less than 10% total organic residues
 Disposal Method: Not reported
 Contact: Not reported
 Telephone: (000) 000-0000
 Mailing Address: 2320 N LINCOLN BLVD
 ALTADENA, CA 91001
 County: Los Angeles

49 U-HAUL CO #713-042 LOS ANGELES CO. HMS S104828056
2320 N LINCOLN AVE N/A
UNINCORPORATED, CA

HMS:

Facility Id: 009406-009213
 Facility Type: T0
 Permit Number: 00000211T Permit Status: Removed
 Facility Status: Removed Area: 3
 Region: Los Angeles County:

50 CHEVRON USA CO LOS ANGELES CO. HMS U003058849
2301 N FAIR OAKS AVE N/A
UNINCORPORATED, CA

HMS:

Facility Id: 002501-102586
 Facility Type: I00
 Permit Number: 000001272 Permit Status: Closed
 Facility Status: Closed Area: 3
 Region: Los Angeles County:

51 LITA MCDONALD-RESIDENCE LOS ANGELES CO. HMS S102592623
365 CROSBY ST N/A
UNINCORPORATED, CA

HMS:

Facility Id: 017890-024541
 Facility Type: Not reported
 Permit Number: Not reported Permit Status: Not reported
 Facility Status: OPEN Area: 3

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

LITA MCDONALD-RESIDENCE (Continued)

S102592623

Region: Los Angeles County:

52

**POPPY CLEANERS
 2271 NORTH LINCOLN AVE
 ALTADENA, CA 91001**

**HAZNET S103982245
 CLEANERS N/A**

CA Cleaners:

Create Date: 04/10/1987
 Inactive Date: 09/16/1998
 EPA Id: CAD981438260
 County : Los Angeles

HAZNET:

Gepaid: CAD981438260
 Tepaid: CAD981397417
 Gen County: Los Angeles
 Tsd County: Los Angeles
 Tons: .0708
 Category: Halogenated solvents (chloroform, methyl chloride, perchloroethylene, etc.)
 Disposal Method: Recycler
 Contact: SONG CHONG YU
 Telephone: (818) 797-7149
 Mailing Address: 2271 LINCOLN AVE
 ALTADENA, CA 91001 - 5468
 County Los Angeles

Gepaid: CAD981438260
 Tepaid: CAD981397417
 Gen County: Los Angeles
 Tsd County: Los Angeles
 Tons: .2774
 Category: Halogenated solvents (chloroform, methyl chloride, perchloroethylene, etc.)
 Disposal Method: Recycler
 Contact: SONG CHONG YU
 Telephone: (818) 797-7149
 Mailing Address: 2271 LINCOLN AVE
 ALTADENA, CA 91001 - 5468
 County Los Angeles

Gepaid: CAD981438260
 Tepaid: CAD981397417
 Gen County: Los Angeles
 Tsd County: Los Angeles
 Tons: .2857
 Category: Halogenated solvents (chloroform, methyl chloride, perchloroethylene, etc.)
 Disposal Method: Recycler
 Contact: SONG CHONG YU
 Telephone: (818) 797-7149
 Mailing Address: 2271 LINCOLN AVE
 ALTADENA, CA 91001 - 5468
 County Los Angeles

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number
 EPA ID Number

Database(s)

POPPY CLEANERS (Continued)

S103982245

Gepaid: CAD981438260
 Tepaid: CAD981397417
 Gen County: Los Angeles
 Tsd County: Los Angeles
 Tons: .2941
 Category: Halogenated solvents (chloroform, methyl chloride, perchloroethylene, etc.)
 Disposal Method: Recycler
 Contact: SONG CHONG YU
 Telephone: (818) 797-7149
 Mailing Address: 2271 LINCOLN AVE
 ALTADENA, CA 91001 - 5468
 County: Los Angeles

52

**PANSY CLEANERS
 2271 N. LINCOLN AVE.
 ALTADENA, CA 91001**

**HAZNET S104577913
 CLEANERS N/A**

CA Cleaners:

Create Date: 09/15/1998
 Inactive Date: 0
 EPA Id: CAL000104871
 County: Los Angeles

HAZNET:

Gepaid: CAL000104871
 Tepaid: CAD981397417
 Gen County: Los Angeles
 Tsd County: Los Angeles
 Tons: .1000
 Category: Halogenated solvents (chloroform, methyl chloride, perchloroethylene, etc.)
 Disposal Method: Recycler
 Contact: SONG RAN KWON
 Telephone: (626) 797-7149
 Mailing Address: 2271 N. LINCOLN AVE.
 ALTADENA, CA 91001
 County: Los Angeles

Gepaid: CAL000104871
 Tepaid: CAD981397417
 Gen County: Los Angeles
 Tsd County: Los Angeles
 Tons: 0.4192
 Category: Halogenated solvents (chloroform, methyl chloride, perchloroethylene, etc.)
 Disposal Method: Recycler
 Contact: SONG RAN KWON
 Telephone: (626) 797-7149
 Mailing Address: 2271 N. LINCOLN AVE.
 ALTADENA, CA 91001
 County: Los Angeles

53

**US POSTAL SERVICE
 2265 N LAKE AVE
 UNINCORPORATED, CA**

**LOS ANGELES CO. HMS U003059380
 N/A**

HMS:

Facility Id: 003074-103184
 Facility Type: Not reported
 Permit Number: Not reported
 Facility Status: OPEN
 Permit Status: Not reported
 Area: 3

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)	Site	Database(s)	EPA ID Number

US POSTAL SERVICE (Continued)

U003059380

Region: Los Angeles County:

**54 PUSD/ALTADENA ELEMENTARY
743 E CALAVERAS ST
ALTADENA, CA 91001**

**HAZNET S105083653
N/A**

HAZNET:

Gepaid:	CAC001439816
Tepaid:	CAD009007626
Gen County:	Los Angeles
Tsd County:	Los Angeles
Tons:	.0000
Category:	Asbestos-containing waste
Disposal Method:	Not reported
Contact:	PASADENA USD
Telephone:	(000) 000-0000
Mailing Address:	740 W WOODBURY RD PASADENA, CA 91103
County	Los Angeles
Gepaid:	CAC001439816
Tepaid:	CAD009007626
Gen County:	Los Angeles
Tsd County:	Los Angeles
Tons:	8.4280
Category:	Asbestos-containing waste
Disposal Method:	Disposal, Land Fill
Contact:	PASADENA USD
Telephone:	(000) 000-0000
Mailing Address:	740 W WOODBURY RD PASADENA, CA 91103
County	Los Angeles
Gepaid:	CAD981433303
Tepaid:	CAD009007626
Gen County:	Los Angeles
Tsd County:	Los Angeles
Tons:	22.75
Category:	Asbestos-containing waste
Disposal Method:	Disposal, Land Fill
Contact:	RALPH RIVERA/ASSIST CONSTRUC
Telephone:	(626) 791-9445
Mailing Address:	740 W WOODBURY RD PASADENA, CA 91103
County	Los Angeles

**55 SCRIPPS RETIREMENT HOME
2212 N EL MOLINO
UNINCORPORATED, CA**

**LOS ANGELES CO. HMS S102058580
N/A**

HMS:

Facility Id:	014357-014935		
Facility Type:	Not reported		
Permit Number:	Not reported	Permit Status:	Not reported
Facility Status:	Removed	Area:	3
Region:	Los Angeles County:		

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number
 EPA ID Number

Database(s)

**55 THE SCRIPPS HOME
 2212 N EL MOLINO
 ALTADENA, CA 91001**

**HAZNET S103642836
 N/A**

HAZNET:
 Gepaid: CAC000878528
 Tepaid: CAD009007626
 Gen County: Los Angeles
 Tsd County: Los Angeles
 Tons: 10.1136
 Category: Asbestos-containing waste
 Disposal Method: Disposal, Land Fill
 Contact: THE SCRIPPS HOME
 Telephone: (000) 000-0000
 Mailing Address: 2212 N EL MOLINO
 ALTADENA, CA 91001
 County Los Angeles
 Gepaid: CAC000878528
 Tepaid: CAD009007626
 Gen County: Los Angeles
 Tsd County: Los Angeles
 Tons: 1.6856
 Category: Asbestos-containing waste
 Disposal Method: Disposal, Land Fill
 Contact: THE SCRIPPS HOME
 Telephone: (000) 000-0000
 Mailing Address: 2212 N EL MOLINO
 ALTADENA, CA 91001
 County Los Angeles

**56 REPUBLIC FEDERAL SAVINGS & LOA
 2246 LAKE AVE
 ALTADENA, CA 91001**

**HIST UST U001566411
 N/A**

UST HIST:
 Facility ID: 391
 Tank Num: 1
 Tank Capacity: 10000
 Tank Used for: PRODUCT
 Type of Fuel: UNLEADED
 Leak Detection: None
 Contact Name: A. J. MATAZINSKI
 Total Tanks: 2
 Facility Type: 2
 Container Num: 1
 Year Installed: 1981
 Tank Construction: Not reported
 Telephone: (818) 791-1281
 Region: STATE
 Other Type: SAVINGS & LOAN
 Facility ID: 391
 Tank Num: 2
 Tank Capacity: 10000
 Tank Used for: PRODUCT
 Type of Fuel: UNLEADED
 Leak Detection: None
 Contact Name: A. J. MATAZINSKI
 Total Tanks: 2
 Facility Type: 2
 Container Num: 2
 Year Installed: 1981
 Tank Construction: Not reported
 Telephone: (818) 791-1281
 Region: STATE
 Other Type: SAVINGS & LOAN

**56 FIRST FED S&L ASSOC
 2246 N LAKE AVE
 UNINCORPORATED, CA**

**LOS ANGELES CO. HMS S104827282
 N/A**

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number
 EPA ID Number

Database(s)

FIRST FED S&L ASSOC (Continued)

S104827282

HMS:

Facility Id: 003149-103263
 Facility Type: Not reported
 Permit Number: Not reported
 Facility Status: OPEN
 Region: Los Angeles County:
 Permit Status: Not reported
 Area: 3

Facility Id: 025505-034973
 Facility Type: Not reported
 Permit Number: Not reported
 Facility Status: OPEN
 Region: Los Angeles County:
 Permit Status: Not reported
 Area: 3E

56

**WEYER HAEUSER FINANCIAL INVESTMENT INC.
 2246 NORTH LAKE AVENUE
 ALTADENA, CA 91001**

**HAZNET S103995765
 N/A**

HAZNET:

Gepaid: CAC001211920
 Tepaid: CAT000646117
 Gen County: Los Angeles
 Tsd County: Kings
 Tons: .2755
 Category: Polychlorinated biphenyls and material containing PCB's
 Disposal Method: Disposal, Land Fill
 Contact: WEYER HAEUSER FINANCIAL
 Telephone: (000) 000-0000
 Mailing Address: 6320 CANOGA AVENUE
 WOODLAND HILLS, CA 91367
 County: Los Angeles

Gepaid: CAC001013232
 Tepaid: CAT000646117
 Gen County: Los Angeles
 Tsd County: Kings
 Tons: .3416
 Category: Polychlorinated biphenyls and material containing PCB's
 Disposal Method: Disposal, Land Fill
 Contact: WEYER HAEUSER FINANCIAL
 Telephone: (000) 000-0000
 Mailing Address: 6320 CANOGA AVENUE
 WOODLAND HILLS, CA 91367
 County: Los Angeles

57

**CHUY'S TIRE SERVICE
 2231 N LINCOLN AVE
 UNINCORPORATED, CA**

**LOS ANGELES CO. HMS S102592712
 N/A**

HMS:

Facility Id: 018046-024887
 Facility Type: Not reported
 Permit Number: Not reported
 Facility Status: OPEN
 Region: Los Angeles County:
 Permit Status: Not reported
 Area: 3

MAP FINDINGS

Map ID			EDR ID Number
Direction			
Distance			
Distance (ft.)Site		Database(s)	EPA ID Number

57	ESQUIRE CLEANERS 2210 N LINCOLN ALTADENA, CA 91001	RCRIS-SQG FINDS CLEANERS	1000425262 CAD981636822
-----------	---	---	--

RCRIS:

Owner: KWANG RO
(818) 791-1477

EPA ID: CAD981636822

Contact: KWANG RO
(818) 791-1477

Classification: Small Quantity Generator
 Used Oil Recyc: No
 TSDF Activities: Not reported

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
 Facility Registry System (FRS)
 Resource Conservation and Recovery Act Information system (RCRAINFO)

CA Cleaners:

Create Date: 04/10/1987
 Inactive Date: 06/30/1998
 EPA Id: CAD981636822
 County : Los Angeles

58	MAINTENANCE DISTRICT #2 815 E CALAVERAS ST ALTADENA, CA 91001	HIST UST	U001566405 N/A
-----------	--	-----------------	---------------------------------

UST HIST:

Facility ID: 33883	
Tank Num: 1	Container Num: RD524A-RG
Tank Capacity: 2000	Year Installed: 1976
Tank Used for: PRODUCT	
Type of Fuel: REGULAR	Tank Construction: 3/16 inches
Leak Detection: Stock Inventor	
Contact Name: JIM MAHONEY	Telephone: (818) 249-3094
Total Tanks: 2	Region: STATE
Facility Type: 2	Other Type: COUNTY GOVERNMENT

Facility ID: 33883	
Tank Num: 2	Container Num: RD524A-D
Tank Capacity: 600	Year Installed: Not reported
Tank Used for: PRODUCT	
Type of Fuel: DIESEL	Tank Construction: 3/16 inches
Leak Detection: Stock Inventor	
Contact Name: JIM MAHONEY	Telephone: (818) 249-3094
Total Tanks: 2	Region: STATE
Facility Type: 2	Other Type: COUNTY GOVERNMENT

58	LA CO DPW ROAD RD DIV 521 815 E CALAVERAS ST UNINCORPORATED, CA	LOS ANGELES CO. HMS	S102056948 N/A
-----------	--	----------------------------	---------------------------------

HMS:

Facility Id: 010429-010345

Facility Type: T1

Permit Number: 000084457

Permit Status: Removed

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number
 Database(s) EPA ID Number

LA CO DPW ROAD RD DIV 521 (Continued)

S102056948

Facility Status: Removed Area: 3
 Region: Los Angeles County

59

**EXXON SERVICE STATION
 2171 FAIR OAKS AVE
 ALTADENA, CA 91001**

**HIST UST U001566397
 N/A**

UST HIST:

Facility ID: 29197
 Tank Num: 1 Container Num: #1
 Tank Capacity: 8000 Year Installed: 1966
 Tank Used for: PRODUCT
 Type of Fuel: PREMIUM Tank Construction: Not reported
 Leak Detection: Stock Inventor
 Contact Name: YEAN YONG HONG Telephone: (213) 798-6477
 Total Tanks: 4 Region: STATE
 Facility Type: 1 Other Type: Not reported

Facility ID: 29197
 Tank Num: 2 Container Num: #2
 Tank Capacity: 8000 Year Installed: 1966
 Tank Used for: PRODUCT
 Type of Fuel: REGULAR Tank Construction: Not reported
 Leak Detection: Stock Inventor
 Contact Name: YEAN YONG HONG Telephone: (213) 798-6477
 Total Tanks: 4 Region: STATE
 Facility Type: 1 Other Type: Not reported

Facility ID: 29197
 Tank Num: 3 Container Num: #3
 Tank Capacity: 8000 Year Installed: 1966
 Tank Used for: PRODUCT
 Type of Fuel: UNLEADED Tank Construction: Not reported
 Leak Detection: Stock Inventor
 Contact Name: YEAN YONG HONG Telephone: (213) 798-6477
 Total Tanks: 4 Region: STATE
 Facility Type: 1 Other Type: Not reported

Facility ID: 29197
 Tank Num: 4 Container Num: #4
 Tank Capacity: 7000 Year Installed: 1966
 Tank Used for: PRODUCT
 Type of Fuel: WASTE OIL Tank Construction: Not reported
 Leak Detection: Stock Inventor
 Contact Name: YEAN YONG HONG Telephone: (213) 798-6477
 Total Tanks: 4 Region: STATE
 Facility Type: 1 Other Type: Not reported

59

**EXXON CO USA #73952
 2171 FAIR OAKS
 ALTADENA, CA 91001**

**HAZNET S103642281
 Cortese N/A**

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number
 EPA ID Number

Database(s)

EXXON CO USA #73952 (Continued)

S103642281

HAZNET:

Gepaid: CAL000002689
 Tepad: CAD028409019
 Gen County: Los Angeles
 Tsd County: Los Angeles
 Tons: .6046
 Category: Waste oil and mixed oil
 Disposal Method: Treatment, Tank
 Contact: EXXON CO USA
 Telephone: (713) 656-7761
 Mailing Address: PO BOX 2180
 HOUSTON, TX 77252 - 2180
 County: Los Angeles

CORTESE:

Reg Id: I-06373
 Region: CORTESE
 Reg By: Leaking Underground Storage Tanks

59

ARCO SMOGPROS
2171 FAIR OAKS AVE
ALTADENA, CA 91001

UST U003777530
LOS ANGELES CO. HMS N/A

HMS:

Facility Id: 006157-036248
 Facility Type: Not reported
 Permit Number: Not reported
 Facility Status: OPEN
 Region: Los Angeles County:
 Permit Status: Not reported
 Area: 3

State UST:

Facility ID: 023625
 Total Tanks: 1
 Region: STATE
 Local Agency: 19000

59

EXXON #7-3952
2171 FAIR OAKS AVE S
ALTADENA, CA 91001

LUST S101295527
N/A

State LUST:

Cross Street: WOODBURY
 Qty Leaked: Not reported
 Case Number: I-06373
 Reg Board: Los Angeles Region
 Chemical: Waste Oil
 Lead Agency: Regional Board
 Local Agency: 19000
 Case Type: Soil only
 Status: Case Closed
 County: Los Angeles
 Review Date: Not reported
 Workplan: 12/26/1991
 Pollution Char: 8/26/1993
 Remed Action: Not reported
 Close Date: 7/17/1996
 Release Date: 12/26/1991
 Cleanup Fund Id: Not reported
 Discover Date: 1/1/1965
 Confirm Leak: Not reported
 Prelim Assess: 12/26/1991
 Remed Plan: 8/26/1993
 Monitoring: Not reported

MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number
EPA ID Number

Database(s)

EXXON #7-3952 (Continued)

S101295527

Enforcement Dt : Not reported
Enf Type: Not reported
Enter Date : 3/14/1992
Funding: Not reported
Staff Initials: Not reported
How Discovered: Tank Closure
How Stopped: Not reported
Interim : Not reported
Leak Cause: UNK
Leak Source: UNK
MTBE Date : Not reported
Max MTBE GW : Not reported
MTBE Tested: Not Required to be Tested.
Priority: Not reported
Local Case # : Not reported
Beneficial: Not reported
Staff : JLC
GW Qualifier : Not reported
Max MTBE Soil : Not reported
Soil Qualifier : Not reported
Hydr Basin #: Not reported
Operator : HOFFMAN, BRADLY
Oversight Prgm: RB Lead Underground Storage Tank
Oversight Prgm : UST
Review Date : 10/25/1996
Stop Date : 7/15/1991
Work Suspended :Not reported
Responsible Party:EXXON COMPANY, U.S.A.
RP Address: P.O. BOX 19649, IRVINE CA 92713-9649 D
Global Id: T0603703206
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0
Mtbe Fuel: 0
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 0
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 4:

Report Date: 12/26/1991
Lead Agency: Regional Board
Local Agency: 19000
Case Number: I-06373
Substance: Waste Oil
Case Type: Soil
Status: Case Closed
Region: 4
Staff: Not reported

59

**STATION 116
2186 FAIR OAKS AVE
ALTADENA, CA 91001**

**HIST UST U001566410
N/A**

UST HIST:

Facility ID: 34275
Tank Num: 1
Tank Capacity: 10000
Container Num: 116-1
Year Installed: Not reported

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number
 EPA ID Number

Database(s)

STATION 116 (Continued)

U001566410

Tank Used for:	WASTE	Tank Construction:	Not reported
Type of Fuel:	REGULAR	Telephone:	(213) 927-5339
Leak Detection:	Stock Inventor	Region:	STATE
Contact Name:	Not reported	Other Type:	Not reported
Total Tanks:	3		
Facility Type:	1		
Facility ID:	34275	Container Num:	116-2
Tank Num:	2	Year Installed:	Not reported
Tank Capacity:	10000	Tank Construction:	Not reported
Tank Used for:	PRODUCT	Telephone:	(213) 927-5339
Type of Fuel:	UNLEADED	Region:	STATE
Leak Detection:	Stock Inventor	Other Type:	Not reported
Contact Name:	Not reported		
Total Tanks:	3		
Facility Type:	1		
Facility ID:	34275	Container Num:	116-3
Tank Num:	3	Year Installed:	Not reported
Tank Capacity:	10000	Tank Construction:	Not reported
Tank Used for:	PRODUCT	Telephone:	(213) 927-5339
Type of Fuel:	PREMIUM	Region:	STATE
Leak Detection:	Stock Inventor	Other Type:	Not reported
Contact Name:	Not reported		
Total Tanks:	3		
Facility Type:	1		

59

CALIFORNIA TARGET #116
2186 FAIR OAKS AVE N
ALTADENA, CA 91001

LUST S101295528
 Cortese N/A
 LOS ANGELES CO. HMS

State LUST:

Cross Street:	WOODBURY STREET	Confirm Leak:	Not reported
Qty Leaked:	Not reported	Prelim Assess:	Not reported
Case Number	I-13862	Remed Plan:	Not reported
Reg Board:	Los Angeles Region	Monitoring:	Not reported
Chemical:	Gasoline		
Lead Agency:	Local Agency		
Local Agency :	19000		
Case Type:	Soil only		
Status:	Case Closed		
County:	Los Angeles		
Review Date:	Not reported		
Workplan:	Not reported		
Pollution Char:	Not reported		
Remed Action:	Not reported		
Close Date:	7/13/1990		
Release Date:	2/26/1990		
Cleanup Fund Id :	Not reported		
Discover Date :	Not reported		
Enforcement Dt :	Not reported		
Enf Type:	Not reported		
Enter Date :	2/19/1990		
Funding:	Not reported		
Staff Initials:	Not reported		
How Discovered:	Not reported		
How Stopped:	Not reported		
Interim :	Not reported		
Leak Cause:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number
EPA ID Number

Database(s)

CALIFORNIA TARGET #116 (Continued)

S101295528

Leak Source: Not reported
MTBE Date : Not reported
Max MTBE GW : Not reported
MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.
Priority: Not reported
Local Case # : Not reported
Beneficial: Not reported
Staff : JLC
GW Qualifier : Not reported
Max MTBE Soil : Not reported
Soil Qualifier : Not reported
Hydr Basin #: Not reported
Operator : Not reported
Oversight Prgm: Local Implementing Agency UST (includes non-LOP cases within LOP jurisdiction)
Oversight Prgm : LIA
Review Date : 8/3/1990
Stop Date : Not reported
Work Suspended :Not reported
Responsible Party:CALIFORNIA TARGET ENT.
RP Address: 517 WISTARIA AVENUE, W., ARCADIA, 91006
Global Id: T0603704115
Org Name: Not reported
Contact Person: Not reported
MTBE Conc: 0
Mtbe Fuel: 1
Water System Name: Not reported
Well Name: Not reported
Distance To Lust: 0
Waste Discharge Global ID: Not reported
Waste Disch Assigned Name: Not reported

LUST Region 4:

Report Date: 2/26/1990
Lead Agency: Local Agency
Local Agency: 19000
Case Number: I-13862
Substance: Gasoline
Case Type: Soil
Status: Case Closed
Region: 4
Staff: Not reported

CORTESE:

Reg Id: I-13862
Region: CORTESE
Reg By: Leaking Underground Storage Tanks

HMS:

Facility Id: 013490-013862
Facility Type: T0
Permit Number: 00005487T
Facility Status: Removed
Region: Los Angeles County:
Permit Status: Removed
Area: 3

59

**UNOCAL SVC STA #2731
2188 N FAIR OAKS
ALTADENA, CA 91001**

**RCRIS-SQG 1000166745
FINDS CAD981646102**

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number
 EPA ID Number

Database(s)

UNOCAL SVC STA #2731 (Continued)

1000166745

RCRIS:

Owner: UNOCAL
 (415) 555-1212
 EPA ID: CAD981646102
 Contact: ENVIRONMENTAL MANAGER
 (213) 977-6227

Classification: Small Quantity Generator
 Used Oil Recyc: No
 TSDF Activities: Not reported
 Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
 Facility Registry System (FRS)
 Resource Conservation and Recovery Act Information system (RCRAINFO)

**59 ABRAHAM'S UNOCAL SERVICE
 2188 N FAIR OAKS
 ALTADENA, CA 91001**

**HAZNET S103948523
 N/A**

HAZNET:

Gepaid: CAL000135485
 Tepaid: CAD099452708
 Gen County: Los Angeles
 Tsd County: Los Angeles
 Tons: 2.5020
 Category: Oil/water separation sludge
 Disposal Method: Recycler
 Contact: BRUNELLA INC
 Telephone: (818) 794-1171
 Mailing Address: 16824 HART STREET
 VAN NUYS, CA 91406 - 4505
 County: Los Angeles

**59 TOSCO CORPORATION STATION #30453
 2188 N FAIR OAKS
 ALTADENA, CA 91001**

**HAZNET S103991889
 N/A**

HAZNET:

Gepaid: CAL000139050
 Tepaid: CAD028409019
 Gen County: Los Angeles
 Tsd County: Los Angeles
 Tons: 11.6760
 Category: Treatment, Tank
 Disposal Method: Treatment, Tank
 Contact: TOSCO MARKETING
 Telephone: (602) 728-4180
 Mailing Address: P O BOX 52085
 PHOENIX, AZ 85072 - 2085
 County: Los Angeles

MAP FINDINGS

Map ID
Direction
Distance
Distance (ft.)Site

EDR ID Number
Database(s) EPA ID Number

TOSCO CORPORATION STATION #30453 (Continued)

S103991889

Gepaid: CAL000139050
Tepaid: CAD028409019
Gen County: Los Angeles
Tsd County: Los Angeles
Tons: .2293
Category: Aqueous solution with less than 10% total organic residues
Disposal Method: Treatment, Tank
Contact: TOSCO MARKETING
Telephone: (602) 728-4180
Mailing Address: P O BOX 52085
PHOENIX, AZ 85072 - 2085
County Los Angeles

59

**UNOCAL SERVICE STATION #2731
2188 N FAIR OAKS
ALTADENA, CA 91001**

**HAZNET S103642397
N/A**

HAZNET:

Gepaid: CAD981646102
Tepaid: CAD028409019
Gen County: Los Angeles
Tsd County: Los Angeles
Tons: .3711
Category: Aqueous solution with less than 10% total organic residues
Disposal Method: Treatment, Tank
Contact: UNION OIL COMPANY OF CALIFORNI
Telephone: (714) 428-6560
Mailing Address: PO BOX 25376
SANTA ANA, CA 92799 - 5376
County Los Angeles

Gepaid: CAD981646102
Tepaid: CAD099452708
Gen County: Los Angeles
Tsd County: Los Angeles
Tons: 3.1275
Category: Waste oil and mixed oil
Disposal Method: Recycler
Contact: UNION OIL COMPANY OF CALIFORNI
Telephone: (714) 428-6560
Mailing Address: PO BOX 25376
SANTA ANA, CA 92799 - 5376
County Los Angeles

Gepaid: CAD981646102
Tepaid: CAD099452708
Gen County: Los Angeles
Tsd County: Los Angeles
Tons: .2293
Category: Tank bottom waste
Disposal Method: Recycler
Contact: UNION OIL COMPANY OF CALIFORNI
Telephone: (714) 428-6560
Mailing Address: PO BOX 25376
SANTA ANA, CA 92799 - 5376
County Los Angeles

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

UNOCAL SERVICE STATION #2731 (Continued)

S103642397

Gepaid: CAD981646102
 Tepaid: CAD028409019
 Gen County: Los Angeles
 Tsd County: Los Angeles
 Tons: 3.3360
 Category: Aqueous solution with 10% or more total organic residues
 Disposal Method: Treatment, Tank
 Contact: UNION OIL COMPANY OF CALIFORNI
 Telephone: (714) 428-6560
 Mailing Address: PO BOX 25376
 SANTA ANA, CA 92799 - 5376
 County: Los Angeles

Gepaid: CAD981646102
 Tepaid: CAT080013352
 Gen County: Los Angeles
 Tsd County: Los Angeles
 Tons: .4587
 Category: Waste oil and mixed oil
 Disposal Method: Recycler
 Contact: UNION OIL COMPANY OF CALIFORNI
 Telephone: (714) 428-6560
 Mailing Address: PO BOX 25376
 SANTA ANA, CA 92799 - 5376
 County: Los Angeles

The CA HAZNET database contains 2 additional records for this site.
 Please contact your EDR Account Executive for more information.

59

**UNOCAL #2731
 2188 FAIR OAKS AVE N
 ALTADENA, CA 91001**

**LUST S101295529
 Cortese N/A**

State LUST:

Cross Street:	WOODBURY	Confirm Leak:	Not reported
Qty Leaked:	Not reported	Prelim Assess:	Not reported
Case Number	I-03578	Remed Plan:	4/4/1994
Reg Board:	Los Angeles Region	Monitoring:	Not reported
Chemical:	Gasoline		
Lead Agency:	Regional Board		
Local Agency :	19000		
Case Type:	Soil only		
Status:	Case Closed		
County:	Los Angeles		
Review Date:	Not reported		
Workplan:	Not reported		
Pollution Char:	4/4/1994		
Remed Action:	Not reported		
Close Date:	8/27/1996		
Release Date:	2/5/1990		
Cleanup Fund Id :	Not reported		
Discover Date :	1/1/1965		
Enforcement Dt :	Not reported		
Enf Type:	Not reported		
Enter Date :	3/28/1990		
Funding:	Federal Funds		
Staff Initials:	Not reported		
How Discovered:	Tank Closure		
How Stopped:	Not reported		

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number
 Database(s) EPA ID Number

UNOCAL #2731 (Continued)

S101295529

Interim : Not reported
 Leak Cause: UNK
 Leak Source: UNK
 MTBE Date : Not reported
 Max MTBE GW : Not reported
 MTBE Tested: Site NOT Tested for MTBE.Includes Unknown and Not Analyzed.
 Priority: Not reported
 Local Case # : Not reported
 Beneficial: Not reported
 Staff : JLC
 GW Qualifier : Not reported
 Max MTBE Soil : Not reported
 Soil Qualifier : Not reported
 Hydr Basin #: Not reported
 Operator : ALBRAHAM, JOSE
 Oversight Prgm: RB Lead Underground Storage Tank
 Oversight Prgm : UST
 Review Date : 5/29/1998
 Stop Date : 1/30/1990
 Work Suspended :Not reported
 Responsible PartyUNOCAL CORPORATION
 RP Address: 376 S VALENCIA AVE., BREA CA 92621
 Global Id: T0603702926
 Org Name: Not reported
 Contact Person: Not reported
 MTBE Conc: 0
 Mtbe Fuel: 1
 Water System Name: Not reported
 Well Name: Not reported
 Distance To Lust: 0
 Waste Discharge Global ID: Not reported
 Waste Disch Assigned Name: Not reported

LUST Region 4:
 Report Date: 2/5/1990
 Lead Agency: Regional Board
 Local Agency: 19000
 Case Number: I-03578
 Substance: Gasoline
 Case Type: Soil
 Status: Case Closed
 Region: 4
 Staff: Not reported

CORTESE:
 Reg Id: I-03578
 Region: CORTESE
 Reg By: Leaking Underground Storage Tanks

 Reg Id: R-24748
 Region: CORTESE
 Reg By: Leaking Underground Storage Tanks

59

**TOSCO/76 STATION #2731
 2188 FAIR OAKS AVE N
 ALTADENA, CA 91001**

**LUST S103891228
 N/A**

State LUST:
 Cross Street: WOODBURG RD
 Qty Leaked: Not reported

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number
 EPA ID Number

Database(s)

TOSCO/76 STATION #2731 (Continued)

S103891228

Case Number R-24748
 Reg Board: Los Angeles Region
 Chemical: Hydrocarbons
 Lead Agency: Regional Board
 Local Agency : 19000
 Case Type: Soil only
 Status: Case Closed
 County: Los Angeles
 Abate Method: Excavate and Dispose - remove contaminated soil and dispose in approved site

Review Date: 3/31/1998
 Workplan: Not reported
 Pollution Char: Not reported
 Remed Action: 2/10/1999
 Close Date: 7/14/1999
 Release Date: 3/31/1998
 Cleanup Fund Id : Not reported
 Discover Date : 1/1/1965
 Enforcement Dt : Not reported
 Enf Type: Not reported
 Enter Date : 12/29/1998
 Funding: Not reported
 Staff Initials: Not reported
 How Discovered: Tank Closure
 How Stopped: Not reported
 Interim : Yes
 Leak Cause: UNK
 Leak Source: UNK
 MTBE Date : 1/1/1965
 Max MTBE GW : Not reported
 MTBE Tested: MTBE Detected. Site tested for MTBE & MTBE detected
 Priority: 2A4
 Local Case # : Not reported
 Beneficial: Not reported
 Staff : GN
 GW Qualifier : Not reported
 Max MTBE Soil : 11 Parts per Million
 Soil Qualifier : Not reported
 Hydr Basin #: Not reported
 Operator : CHRISTOPHER SWARTZ
 Oversight Prgm: RB Lead Underground Storage Tank
 Oversight Prgm : UST
 Review Date : 6/24/1999
 Stop Date : 2/18/1998
 Work Suspended : Not reported
 Responsible Party: TOSCO CORP.
 RP Address: P.O. BOX 25376, SANTA ANA, CA 94798-5376
 Global Id: T0603705463
 Org Name: Not reported
 Contact Person: Not reported
 MTBE Conc: 1
 Mtbe Fuel: 0
 Water System Name: Not reported
 Well Name: Not reported
 Distance To Lust: 0
 Waste Discharge Global ID: Not reported
 Waste Disch Assigned Name: Not reported

Confirm Leak: 3/31/1998
 Prelim Assess: Not reported
 Remed Plan: Not reported
 Monitoring: 2/10/1999

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number
 EPA ID Number

Database(s)

TOSCO/76 STATION #2731 (Continued)

S103891228

LUST Region 4:
 Report Date: 3/31/1998
 Lead Agency: Regional Board
 Local Agency: 19000
 Case Number: R-24748
 Substance: Hydrocarbons
 Case Type: Soil
 Status: Case Closed
 Region: 4
 Staff: GN

59

**UNOCAL SERVICE STATION
 2188 N FAIR OAKS AVE
 ALTADENA, CA 91001**

**CA FID UST S101583034
 LOS ANGELES CO. HMS N/A**

FID:

Facility ID:	19002334	Regulate ID:	CAD981646
Reg By:	Inactive Underground Storage Tank Location	SIC Code:	Not reported
Cortese Code:	Not reported	Facility Tel:	(818) 794-1171
Status:	Inactive		
Mail To:	Not reported		
	17700 CASTLETON ST ALTADENA, CA 91001		
Contact:	Not reported	Contact Tel:	Not reported
DUNs No:	Not reported	NPDES No:	Not reported
Creation:	10/22/93	Modified:	00/00/00
EPA ID:	Not reported		
Comments:	Not reported		

Facility ID:	19002334	Regulate ID:	CAD981646
Reg By:	Active Underground Storage Tank Location	SIC Code:	Not reported
Cortese Code:	Not reported	Facility Tel:	(805) 257-3915
Status:	Active		
Mail To:	Not reported		
	911 WILSHIRE BLVD CASTAIC, CA 91384		
Contact:	Not reported	Contact Tel:	Not reported
DUNs No:	Not reported	NPDES No:	Not reported
Creation:	10/22/93	Modified:	00/00/00
EPA ID:	Not reported		
Comments:	Not reported		

HMS:

Facility Id:	003459-024748	Permit Status:	Removed
Facility Type:	T0	Area:	3
Permit Number:	000190325		
Facility Status:	Removed		
Region:	Los Angeles County:		

59

**SERVICE STATION 2731
 2188 FAIR OAKS AVE
 ALTADENA, CA 91101**

**HIST UST U001566670
 N/A**

UST HIST:

Facility ID:	29424	Container Num:	1
Tank Num:	1	Year Installed:	1969
Tank Capacity:	12000		
Tank Used for:	PRODUCT		

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number
 Database(s) EPA ID Number

SERVICE STATION 2731 (Continued)

U001566670

Type of Fuel: DIESEL Leak Detection: Stock Inventor, Pressure Test Contact Name: JOSE ABRAHAM Total Tanks: 5 Facility Type: 1	Tank Construction: Not reported Telephone: (818) 794-1171 Region: STATE Other Type: Not reported
Facility ID: 29424 Tank Num: 2 Tank Capacity: 12000 Tank Used for: PRODUCT Type of Fuel: DIESEL Leak Detection: Stock Inventor, Pressure Test Contact Name: JOSE ABRAHAM Total Tanks: 5 Facility Type: 1	Container Num: 2731-3 Year Installed: 1969 Tank Construction: Not reported Telephone: (818) 794-1171 Region: STATE Other Type: Not reported
Facility ID: 29424 Tank Num: 3 Tank Capacity: 9940 Tank Used for: PRODUCT Type of Fuel: UNLEADED Leak Detection: Stock Inventor, Pressure Test Contact Name: JOSE ABRAHAM Total Tanks: 5 Facility Type: 1	Container Num: 2731-1 Year Installed: 1969 Tank Construction: Not reported Telephone: (818) 794-1171 Region: STATE Other Type: Not reported
Facility ID: 29424 Tank Num: 4 Tank Capacity: 9940 Tank Used for: PRODUCT Type of Fuel: PREMIUM Leak Detection: Stock Inventor, Pressure Test Contact Name: JOSE ABRAHAM Total Tanks: 5 Facility Type: 1	Container Num: 2731-2 Year Installed: 1969 Tank Construction: Not reported Telephone: (818) 794-1171 Region: STATE Other Type: Not reported
Facility ID: 29424 Tank Num: 5 Tank Capacity: 550 Tank Used for: WASTE Type of Fuel: WASTE OIL Leak Detection: Stock Inventor, Pressure Test Contact Name: JOSE ABRAHAM Total Tanks: 5 Facility Type: 1	Container Num: 2731-4 Year Installed: 1968 Tank Construction: Not reported Telephone: (818) 794-1171 Region: STATE Other Type: Not reported

59

UNION OIL SERVICE STATION #273
2188 FAIR OAKS AVE
ALTADENA, CA 91101

HIST UST U001566676
N/A

UST HIST:

Facility ID: 56102 Tank Num: 1 Tank Capacity: 0 Tank Used for: WASTE Type of Fuel: Not Reported Leak Detection: None Contact Name: JOSE ABRAHAM Total Tanks: 1	Container Num: 2731-00 Year Installed: Not reported Tank Construction: Not reported Telephone: (818) 794-1171 Region: STATE
---	---

MAP FINDINGS

Map ID		EDR ID Number
Direction		
Distance		
Distance (ft.)Site		Database(s) EPA ID Number

62	COMMUNITY DEVELOPMENT COMMISSION 383 ACACIA STREET ALTADENA, CA 91001	HAZNET	S104572253 N/A
-----------	--	---------------	---------------------------------

HAZNET:

Gepaid:	CAC002216905
Tepaid:	CAD009007626
Gen County:	Los Angeles
Tsd County:	Los Angeles
Tons:	0.8428
Category:	Asbestos-containing waste
Disposal Method:	Disposal, Land Fill
Contact:	COMMUNITY DEVELOPMENT COMM.
Telephone:	(323) 890-7108
Mailing Address:	2 CORAL CIRCLE
	MONTEREY PARK, CA 91755
County:	Los Angeles

63	EXXON CO USA 2185 N LINCOLN AVE UNINCORPORATED, CA	LOS ANGELES CO. HMS	U003060498 N/A
-----------	---	----------------------------	---------------------------------

HMS:

Facility Id:	004296-104451		
Facility Type:	I00		
Permit Number:	000002007	Permit Status:	Closed
Facility Status:	Closed	Area:	3
Region:	Los Angeles County:		

63	94766 2157 LINCOLN AVE ALTADENA, CA 91001	HIST UST	U001566394 N/A
-----------	--	-----------------	---------------------------------

UST HIST:

Facility ID:	62670		
Tank Num:	1	Container Num:	1
Tank Capacity:	10000	Year Installed:	1970
Tank Used for:	PRODUCT		
Type of Fuel:	Not Reported	Tank Construction:	0000250 unknown
Leak Detection:	Stock Inventor		
Contact Name:	ABU-JABER,FARES T	Telephone:	(818) 794-1749
Total Tanks:	4	Region:	STATE
Facility Type:	1	Other Type:	Not reported
Facility ID:	62670		
Tank Num:	2	Container Num:	2
Tank Capacity:	10000	Year Installed:	1970
Tank Used for:	PRODUCT		
Type of Fuel:	Not Reported	Tank Construction:	0000250 unknown
Leak Detection:	Stock Inventor		
Contact Name:	ABU-JABER,FARES T	Telephone:	(818) 794-1749
Total Tanks:	4	Region:	STATE
Facility Type:	1	Other Type:	Not reported
Facility ID:	62670		
Tank Num:	3	Container Num:	3
Tank Capacity:	5000	Year Installed:	1970
Tank Used for:	PRODUCT		
Type of Fuel:	Not Reported	Tank Construction:	0000250 unknown
Leak Detection:	Stock Inventor		

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number
 EPA ID Number

Database(s)

94766 (Continued)

U001566394

Contact Name:	ABU-JABER,FARES T	Telephone:	(818) 794-1749
Total Tanks:	4	Region:	STATE
Facility Type:	1	Other Type:	Not reported
Facility ID:	62670		
Tank Num:	4	Container Num:	4
Tank Capacity:	1000	Year Installed:	1970
Tank Used for:	WASTE		
Type of Fuel:	Not Reported	Tank Construction:	0000130 unknown
Leak Detection:	Stock Inventor		
Contact Name:	ABU-JABER,FARES T	Telephone:	(818) 794-1749
Total Tanks:	4	Region:	STATE
Facility Type:	1	Other Type:	Not reported

64

**7073 WOODBURY ROAD
 ALTADENA, CA**

**CHMIRS S100279944
 N/A**

CHMIRS:

OES Control Number:	9014291	DOT ID:	Not reported
DOT Hazard Class:	Not Reported		
Chemical Name:	PRINTING PRESS CLEANER-SOLVENT(TRADE NAME ML2)		
Extent of Release:	Not reported		
CAS Number:	Not reported	Quantity Released:	5
Environmental Contamination:	Ground	Property Use:	Industrial, Utility
Incident Date:	05-DEC-90	Date Completed:	05-DEC-90
Time Completed :	210		
Physical State Stored :	Liquid		
Physical State Released :	Liquid		
Release Unit :	Gallons		
Container Description :	2		
Container Type :	19		
Container Material :	Plastic Fiberglass , Rigid		
Level Of Container :	10		
Container Capacity :	5		
Container Capacity Units (code) :	Gallons		
Extent Of Release (code) :	6		
Agency Id Number :	19110		
Agency Incident Number :	2		
OES Incident Number :	9014291		
Time Notified :	28		
Surrounding Area :	600		
Estimated Temperature :	50		
Property Management :	P		
More Than Two Substances Involved? :	Not reported		
Special Studies 1 :	Not reported		
Special Studies 2 :	Not reported		
Special Studies 3 :	Not reported		
Special Studies 4 :	Not reported		
Special Studies 5 :	Not reported		
Special Studies 6 :	Not reported		
Responding Agency Personel # Of Injuries :	0		
Responding Agency Personel # Of Fatalities :	0		
Resp Agncy Personel # Of Decontaminated :	0		
Others Number Of Decontaminated :	0		
Others Number Of Injuries :	0		
Others Number Of Fatalities :	0		
Vehicle Make/year :	Not reported		
Vehicle License Number :	Not reported		

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number
 EPA ID Number

Database(s)

(Continued)

S100279944

Vehicle State :	Not reported
Vehicle Id Number :	Not reported
CA/DOT/PUC/ICC Number :	Not reported
Company Name :	Not reported
Reporting Officer Name/ID :	LYNN A. MOHR, CAPT. 124351
Report Date :	05-DEC-90
Comments :	Yes
Facility Telephone Number :	213 267-2401
Waterway Involved :	Not reported
Waterway :	Not reported
Spill Site :	Not reported
Cleanup By :	Not reported
Containment :	Not reported
What Happened :	Not reported
Date/Time :	Not reported
Evacuations :	Not reported
Type :	Not reported
Other :	Not reported
Chemical 1 :	Not Reported
Chemical 2 :	Not Reported
Chemical 3 :	Not Reported

64 **PAUL ROBERTS**
 2209 N EL SOL
 ALTADENA, CA 91001

CA FID UST S101587257
 N/A

FID:

Facility ID:	19055160	Regulate ID:	Not reported
Reg By:	Active Underground Storage Tank Location		
Cortese Code:	Not reported	SIC Code:	Not reported
Status:	Active	Facility Tel:	(818) 298-0725
Mail To:	Not reported		
	3228 ALANREED AVE		
	ALTADENA, CA 91001		
Contact:	Not reported	Contact Tel:	Not reported
DUNs No:	Not reported	NPDES No:	Not reported
Creation:	10/22/93	Modified:	00/00/00
EPA ID:	Not reported		
Comments:	Not reported		

65 **EXXON USA #7-3952**
 2171 N FAIR OAKS AVE
 UNINCORPORATED, CA

LOS ANGELES CO. HMS S102058549
 N/A

HMS:

Facility Id:	006157-006373		
Facility Type:	T0		
Permit Number:	00003537T	Permit Status:	Removed
Facility Status:	Removed	Area:	3
Region:	Los Angeles County:		

65 **ARCO SMOGPROS**
 2171 N FAIR OAKS AVE
 UNINCORPORATED, CA

LOS ANGELES CO. HMS S102229316
 N/A

HMS:

Facility Id:	006157-023625
Facility Type:	T0

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number
 EPA ID Number

Database(s)

1X MOBIL OIL #11 LAB (Continued)

S104576720

Gepaid: CAL000056217
 Tepaid: CAT080011059
 Gen County: Los Angeles
 Tsd County: Los Angeles
 Tons: .1334
 Category: Aqueous solution with 10% or more total organic residues
 Disposal Method: Recycler
 Contact: MOBIL
 Telephone: (703) 846-5734
 Mailing Address: PO BOX 142667
 AUSTIN, TX 78714 - 2667
 County: Los Angeles

Gepaid: CAL000056217
 Tepaid: CAD028409019
 Gen County: Los Angeles
 Tsd County: Los Angeles
 Tons: .1876
 Category: Aqueous solution with less than 10% total organic residues
 Disposal Method: Treatment, Tank
 Contact: MOBIL
 Telephone: (703) 846-5734
 Mailing Address: PO BOX 142667
 AUSTIN, TX 78714 - 2667
 County: Los Angeles

Gepaid: CAL000056217
 Tepaid: CAD028409019
 Gen County: Los Angeles
 Tsd County: Los Angeles
 Tons: 2.2763
 Category: Unspecified oil-containing waste
 Disposal Method: Treatment, Tank
 Contact: MOBIL
 Telephone: (703) 846-5734
 Mailing Address: PO BOX 142667
 AUSTIN, TX 78714 - 2667
 County: Los Angeles

Gepaid: CAL000056217
 Tepaid: Not reported
 Gen County: Los Angeles
 Tsd County: 0
 Tons: .2710
 Category: Unspecified oil-containing waste
 Disposal Method: Treatment, Tank
 Contact: MOBIL
 Telephone: (703) 846-5734
 Mailing Address: PO BOX 142667
 AUSTIN, TX 78714 - 2667
 County: Los Angeles

The CA HAZNET database contains 10 additional records for this site.
 Please contact your EDR Account Executive for more information.

65

**MOBIL OIL CORP S/S #18-LAB
 15 W WOODBURY RD
 ALTADENA, CA 91001**

**UST U003775855
 N/A**

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number
 EPA ID Number

Database(s)

MOBIL OIL CORP S/S #18-LAB (Continued)

U003775855

State UST:

Facility ID: 000912
 Total Tanks: 1
 Region: STATE
 Local Agency: 19000

UST San Francisco County:

Facility ID: 912	Case Number: Not reported
Tank ID: Not reported	Owner Name: Not reported
Receive Date: 9/30/91	Close Date: Not reported

Certified Date: Not reported	Number Of Tanks : 1
Mailing Address: Not reported	Location Within Site: Not reported
Care Of Address : Not reported	Tank Manufacturer: Not reported
Type Of Action : Not reported	Compartmentalized Tank : Not reported
Local Tank Id : Not reported	Date Tank Installed : Not reported
Compartmentalized Tank :	Tank Capacity : Not reported
Date Tank Installed :	# Of Tank Compartments : Not reported
Tank Capacity :	Additional Desc : Not reported
# Of Tank Compartments :	Petroleum Type : Not reported
Additional Desc : Not reported	Tank Use : Not reported
Petroleum Type : Not reported	Common Name : Not reported
Type Of Tank :	Tank Material - Primary Tank : Not reported
Type Of Tank :	Tank Material - Secondary Tank : Not reported
Tank Material - Primary Tank :	Tank Interior Lining/coating : Not reported
Tank Material - Secondary Tank :	Tank Int Lining Install Dt: Not reported
Tank Interior Lining/coating :	Other Tank Corrosive Protection : Not reported
Tank Int Lining Install Dt:	Date Tank Corrosive Protection Install : Not reported
Other Tank Corrosive Protection :	Year Spill And Overfill Installed :
Date Tank Corrosive Protection Install :	Spill Containment : Not reported
Year Spill And Overfill Installed :	Drop Tube : Not reported
Spill Containment :	Striker Plate : Not reported
Drop Tube :	Type Of Spill Protection :
Striker Plate :	Spill Containment : Not reported
Type Of Spill Protection :	Drop Tube : Not reported
Spill Containment :	Striker Plate : Not reported
Drop Tube :	Year Overfill Protection Equipment Installed :
Striker Plate :	Alarm : Not reported
Year Overfill Protection Equipment Installed :	Ball Float : Not reported
Alarm :	Fill Tube Shut : Not reported
Ball Float :	Exempt : Not reported
Fill Tube Shut :	Tank Leak Detection (Single Wall) :
Exempt :	Visual (Exposed Portion) : Not reported
Tank Leak Detection (Single Wall) :	Automatic Tank Gauging : Not reported
Visual (Exposed Portion) :	Continuous Atg : Not reported
Automatic Tank Gauging :	Statscl Invntry Reconciliation & Biennial Tank Test : Not reported
Continuous Atg :	Manual Tank Gauging : Not reported
Statscl Invntry Reconciliation & Biennial Tank Test :	Vadose Zone Tank Leak Detection : Not reported
Manual Tank Gauging :	Groundwater : Not reported
Vadose Zone Tank Leak Detection :	Tank Testing : Not reported
Groundwater :	Other Detection : Not reported
Tank Testing :	Tank Leak Detection (Double Wall) :
Other Detection :	Visual (Single Wall In Vault Only) : Not reported
Tank Leak Detection (Double Wall) :	Continuous Interstitial Monitoring : Not reported
Visual (Single Wall In Vault Only) :	Manual Monitoring : Not reported
Continuous Interstitial Monitoring :	Estimated Date Last Used : Not reported
Manual Monitoring :	Estimated Qty Of Substance Remaining : Not reported
Estimated Date Last Used :	
Estimated Qty Of Substance Remaining :	

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number
 EPA ID Number

Database(s)

MOBIL OIL CORP S/S #18-LAB (Continued)

U003775855

Tank Filled With Inert Material :	Not reported
Piping System Type (Underground) :	
Pressure :	Not reported
Suction :	Not reported
Gravity :	Not reported
Piping System Type (Aboveground) :	
Pressure :	Not reported
Suction :	Not reported
Gravity :	Not reported
Piping Construction (Underground) :	
Single Wall :	Not reported
Double Wall :	Not reported
Lined Trench :	Not reported
Unknown :	Not reported
Other :	Not reported
Piping Manufacturer (Underground) :	Not reported
Piping Construction (Aboveground) :	
Single Wall :	Not reported
Double Wall :	Not reported
Unknown :	Not reported
Other :	Not reported
Piping Manufacturer (Aboveground) :	Not reported
Piping Mat. And Corrosion Protection (Underground) :	
Bare Steel :	Not reported
Stainless Steel :	Not reported
Plastic Compatible With Contents :	Not reported
Fiberglass :	Not reported
Steel W/coating :	Not reported
FRP Compatible W/100% Methanol :	Not reported
Galvanized Steel :	Not reported
Flexible (HDPE - High Density Polyethylene) :	Not reported
Cathodic Protection :	Not reported
Unknown :	Not reported
Other :	Not reported
Piping Mat. & Corrosion Protec (Aboveground) :	
Bare Steel :	Not reported
Stainless Steel :	Not reported
Plastic Compatible With Contents :	Not reported
Fiberglass :	Not reported
Steel W/coating :	Not reported
Frp Compatible W/100% Methanol :	Not reported
Galvanized Steel :	Not reported
Flexible (HDPE - High Density Polyethylene) :	Not reported
Cathodic Protec n :	Not reported
Unknown :	Not reported
Other :	Not reported
Piping Leak Detection (Underground - Single Wall) :	
Electronic Line Leak Detector/ Auto Shutoff/ Alarms :	Not reported
Monthly 0.2 Gph Test :	Not reported
Annual Integrity Test :	Not reported
Daily Visual Monitrng ,Trienn Integrity Test :	Not reported
Self Monitoring :	Not reported
Biennial Integrity Test :	Not reported
Piping Leak Detection (Secondarily Contained) :	
Sump Sensor, Alarms ,Auto Shutoff For Leaks :	Not reported
Sump Snsr, Alm ,Auto Shutoff For Leaks, Failure, & Disconnect :	Not reported
Sump Sensor ,Alarms ,No Auto Shutoff :	Not reported

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

MOBIL OIL CORP S/S #18-LAB (Continued)

U003775855

Pressure, Auto Leak Detctr ,Flow Shutoff Or Restrctn Not reported
 Annual Integrity Test : Not reported
 Suction,Gravity ,Sump Sensor,Alarms : Not reported
 Piping Leak Detection (Emergency Generators) :
 Sump Sensor W/O Auto Shutoff /Alarms : Not reported
 Auto Leak Detector W/O Flow Shutoff Or Restrctn : Not reported
 Annual Integrity Test : Not reported
 Piping Leak Detecn Abvegrnd - Emrgncy Gen - Daily Visual Chk :Not reported
 Pipe Integrity Test, Underground : Not reported
 Piping Leak Detection (Aboveground - Single Wall) :
 Electronic Line Leak Detector /Auto Shutoff /Alarms : Not reported
 Monthly 0.2 Gph Test : Not reported
 Annual Integrity Test : Not reported
 Single Wall, Pressure Daily Visual Check : Not reported
 Single Wall, Suction - Daily Visual Monitoring : Not reported
 Triennial Integrity Test : Not reported
 Self Monitoring : Not reported
 Single Wall, Gravity - Daily Visual Monitoring : Not reported
 Biennial Integrity Test : Not reported
 Piping Leak Detection (Aboveground - Secondly Contained)
 Sump Sensor, Alarms, Auto Shutoff For Leaks : Not reported
 Piping Leak Detection (Underground - Secondly Contained)
 Sump Snsr, Alarm , Auto Shutoff For Leaks, Failre & Disconct : Not reported
 Sump Sensor, Alarms, No Auto Shutoff : Not reported
 Pressure - Auto Leak Detctr, Flow Shutoff /Restrctn : Not reported
 Annual Integrity Test : Not reported
 Suction/gravity - Sump Sensor , Alarms : Not reported
 Piping Leak Detection Underground (Emergency Generators)
 Sump Sensor Without Auto Shutoff , Alarms : Not reported
 Auto Leak Detector W/o Flow Shutoff Or Restrctn : Not reported
 Annual Integrity Test : Not reported
 Daily Visual Check : Not reported
 Pipe Integrity Test, Aboveground : Not reported
 Date Dispenser Containment Installed : Not reported
 Dispenser Containment Type : Not reported
 Date Certified (Tank Unit) : Not reported
 Owner/ Operator Name (Tank Unit) : Not reported
 Owner/ Operator Title (Tank Unit) : Not reported
 Permit Number : Not reported
 Permit Approved By : Not reported
 Permit Expiration Date : Not reported
 Last Annual Monitoring Cert: Not reported
 Secondary Containment Test : Not reported
 Spill Containment Present : Not reported
 Drop Tube Present : Not reported
 Striker Plate Present : Not reported
 Alarm Present : Not reported
 Ball Float Present : Not reported
 Fill Tube Present : Not reported
 Other Tank Leak Detection Present : Not reported

65

**MOBIL OIL CORP
 15 W WOODBURY RD
 ALTADENA, CA 91001**

**RCRIS-SQG 1000905473
 FINDS CA0000744334**

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number

Database(s) EPA ID Number

MOBIL OIL CORP (Continued)

1000905473

RCRIS:

Owner: MOBIL OIL CORP
 (703) 846-5712
 EPA ID: CA0000744334
 Contact: WYATT DUNBAR
 (703) 846-5712
 Classification: Small Quantity Generator
 Used Oil Recyc: No
 TSDF Activities: Not reported
 Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
 Facility Registry System (FRS)
 Resource Conservation and Recovery Act Information system (RCRAINFO)

65	UNOCAL CORP SS 2731 2188 N FAIR OAKS AVE UNINCORPORATED, CA	LOS ANGELES CO. HMS	U002279056 N/A
-----------	--	----------------------------	---------------------------

HMS:

Facility Id: 003459-I03578	
Facility Type: I01	
Permit Number: 000001549	Permit Status: Closed
Facility Status: Closed	Area: 3
Region: Los Angeles County:	

Facility Id: 003459-003578	
Facility Type: T0	
Permit Number: 00001381T	Permit Status: Closed
Facility Status: Permit	Area: 3
Region: Los Angeles County:	

65	MOBIL OIL SS 11LAB 15 W WOODBURY RD UNINCORPORATED, CA	LOS ANGELES CO. HMS	U002277951 N/A
-----------	---	----------------------------	---------------------------

HMS:

Facility Id: 000873-I00912	
Facility Type: I01	
Permit Number: 000010045	Permit Status: Permit
Facility Status: Permit	Area: 3
Region: Los Angeles County:	

Facility Id: 000873-020520	
Facility Type: Not reported	
Permit Number: Not reported	Permit Status: Not reported
Facility Status: OPEN	Area: 3
Region: Los Angeles County:	

66	MOBIL OIL CORP 2172 N ARROYO BLVD UNINCORPORATED, CA	LOS ANGELES CO. HMS	S102531847 N/A
-----------	---	----------------------------	---------------------------

HMS:

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number
 EPA ID Number

Database(s)

MOBIL OIL CORP (Continued)

S102531847

Facility Id: 003106-103217
 Facility Type: 100
 Permit Number: 000001335
 Facility Status: Closed
 Region: Los Angeles County

Permit Status: Closed
 Area: 3

67

**JACKSON ELEMENTARY
 593 W WOODBURY RD
 ALTADENA, CA 91001**

**HAZNET S105084315
 N/A**

HAZNET:

Gepaid: CAC002194881
 Tepaid: CAD009007626
 Gen County: Los Angeles
 Tsd County: Los Angeles
 Tons: 8.4280
 Category: Asbestos-containing waste
 Disposal Method: Disposal, Land Fill
 Contact: PASADENA U S D
 Telephone: (626) 798-6773
 Mailing Address: 593 W WOODBURY RD
 ALTADENA, CA 91001
 County: Los Angeles

Gepaid: CAC002194881
 Tepaid: CAD009007626
 Gen County: Los Angeles
 Tsd County: Los Angeles
 Tons: 25.2840
 Category: Asbestos-containing waste
 Disposal Method: Not reported
 Contact: PASADENA U S D
 Telephone: (626) 798-6773
 Mailing Address: 593 W WOODBURY RD
 ALTADENA, CA 91001
 County: Los Angeles

Gepaid: CAD981432339
 Tepaid: CAD028409019
 Gen County: Los Angeles
 Tsd County: Los Angeles
 Tons: 0
 Category: Other organic solids
 Disposal Method: Transfer Station
 Contact: RALPH RIVERA/ASSIST CONSTRUCT
 Telephone: (626) 791-9445
 Mailing Address: 740 W WOODBURY RD
 PASADENA, CA 91103
 County: Los Angeles

Gepaid: CAD981432339
 Tepaid: CAD009007626
 Gen County: Los Angeles
 Tsd County: Los Angeles
 Tons: 0.84
 Category: Asbestos-containing waste
 Disposal Method: Disposal, Land Fill
 Contact: RALPH RIVERA/ASSIST CONSTRUCT
 Telephone: (626) 791-9445
 Mailing Address: 740 W WOODBURY RD

MAP FINDINGS

Map ID
 Direction
 Distance
 Distance (ft.)Site

EDR ID Number
 EPA ID Number

Database(s)

JACKSON ELEMENTARY (Continued)

S105084315

County PASADENA, CA 91103
 Los Angeles

67

GREEN BROS INC
543 W WOODBURY RD
UNINCORPORATED, CA

LOS ANGELES CO. HMS

S102056522
N/A

HMS:

Facility Id:	009358-009161	Permit Status:	Closed
Facility Type:	T0	Area:	3
Permit Number:	00000145T		
Facility Status:	Closed		
Region:	Los Angeles County:		

68

GREEN BROS INC
543 W WOODBURY RD
ALTADENA, CA 91001

UST U001566399
HIST UST N/A

UST HIST:

Facility ID:	55296	Container Num:	1
Tank Num:	1	Year Installed:	Not reported
Tank Capacity:	3000		
Tank Used for:	PRODUCT	Tank Construction:	Not reported
Type of Fuel:	DIESEL		
Leak Detection:	None	Telephone:	(213) 681-8775
Contact Name:	JACK L. GREEN	Region:	STATE
Total Tanks:	2	Other Type:	DEMOLITION
Facility Type:	2		

Facility ID:	55296	Container Num:	2
Tank Num:	2	Year Installed:	Not reported
Tank Capacity:	3000		
Tank Used for:	PRODUCT	Tank Construction:	Not reported
Type of Fuel:	REGULAR		
Leak Detection:	None	Telephone:	(213) 681-8775
Contact Name:	JACK L. GREEN	Region:	STATE
Total Tanks:	2	Other Type:	DEMOLITION
Facility Type:	2		

State UST:

Facility ID:	009161
Total Tanks:	1
Region:	STATE
Local Agency:	19000

68

OA0 CORP
500 W WOODBURY RD
UNINCORPORATED, CA

LOS ANGELES CO. HMS

U003063806
N/A

HMS:

Facility Id:	008096-108609	Permit Status:	Removed
Facility Type:	I01	Area:	3
Permit Number:	000012837		
Facility Status:	Removed		
Region:	Los Angeles County:		